

## **INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS**

Janpath, New Delhi -110 001, www.ignca.gov.in

## **Documentation format for Archaeological / Heritage Sites / Monuments**

Serial No.: 0R / PRI- 43

**SECTION I: IDENTIFICATION** 1. Name Kumaresvara Temple, Indipur (Malisahi.), Dist. - Puri Present Past Other Name (if any): 2. Location **LONGITUDE** 85<sup>0</sup> 43' 53" E 19<sup>0</sup> 59' 34" N LATITUDE **ELEVATION** 28 ft **Address** Village (village code) Indipur(Malisahi) Post:Indipur Via: Satyabadi **Tehsil:** Satyabadi **District:** Puri State: Orissa **PIN:** 752016 Approach The temple is located on the right side of the road leading from Delang station to Brahmagiri and it is about 20km, from Pipili and 14km, from Sakhiqopal and 8km. from Delang station. 3. Property Type **Buildings** Religious structures Other Structures Temple Wall Palace Fort Mosque Gateway Pillar Citadel Minar Govt. building Church Others (specify) Railway station Monastery Defense building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Engineering structure Open space and related Note: structures The temple has a rekha vimana Bridge Public square pidha jagamohana Park or garden Kalingan order... Tunnel Other engineering structure Graveyard Baolis, Well Tank Cave

4. Property Use ABANDONED / IN USE: In use Present It is a living temple, the presiding deity is a patalaphuta Sivalinga within a circular yonipatha made of black chlorite and it is 1.20mts below the entrance level. **Past** Worshipped. 5. Age (Source) Ganga rule. PERIOD 14<sup>th</sup> century A.D. YEARS 14<sup>th</sup> century A.D. **Precise date of Construction** Completion Subsequent changes Orissa State Archaeology ,renovated this temple under X and XI Finance Commission Award **Destruction / Demolition** 6. Ownership / Level of Protection SINGLE /MULTIPLE : Multiple. **Public**: Archaeological Survey of : Protected monument of Orissa State Archaeology. State Archaeology Department / Any Other (Please specify) **Private** Any other (Please specify) Under the sevayats headed by Banamali Panda. Name Orissa State Archaeology Address Paryatana Bhawan, B.J.B.Nagar, Bhubaneswar, Orissa. Phone 0674-2432147. 7. Association WITH EVENTS In History In Rituals Sivaratri,kartikapurnima,Sankrati etc. In Building Construction Any other (specify) Thread ceremony, marriage, engagements etc. held

WITH PERSONS

Originally the Gangas, but now the Orissa State **Patron** 

Archaeology.

Architect / Engineer

Any other (specify) Banamali Panda the head of the Sevayatas.

## 8. Statement of Significance

	Architectural Archaeological			hitect haeo	tural. logical.					
Ī	Historical									
Ī	Religious									
	Any other (specify)	:	On	the	basis	of	architectural	features	and	sculptura

## **SECTION II: DESCRIPTION**

9. Physical Description and Decorative Features							
<ul> <li>Context</li> <li>Urban / Rural Setting</li> <li>Surroundings</li> </ul>	* <b>Drawings (</b> Attach extra sheet if necessary):No Rural setting						
J	Stand in isolation Complex. Integral part of a landscape / Street / Complex :						
• Quantification Area Dimension ( L x B x H)	: 15.25mtrs. x 7.70mtrs. x 13.00mtrs.(approximate.)						
Number of Blocks	(m / cm/ feet / inch)						
Number of Storys	: Two :						
Spatial Organization							
Orientation Plan	<ul> <li>The temple is facing towards east.</li> <li>Consists of a square <i>vimana</i> and a <i>jagamohana</i> joined by an <i>antarala</i> which stands over a low height <i>khura</i> style of <i>upana</i> .</li> </ul>						
Allocation of Spaces	:						
• Ornamentation							
Exteriors	: Decorated with architectural motifs such as <i>pidhamundis, khakharamundi, rekamundis, Naga-Nagi</i> pilasters.Semidivinitieslike- <i>Dikpalas; Mithuna, Maithuna, Gaja-vidalas,</i> elephants procession, scroll work, Vamana <i>avatara</i> , risi, <i>nayikas,</i> royal procession, scroll work etc.						
Interiors Movable Collections	<ul><li>: Plain</li><li>: Few architectural member.</li></ul>						
* Any Other (specify)	<ul><li>: Few architectural member.</li><li>: Both <i>vimana</i> and <i>jagamohana</i> are <i>saptaratha</i> on plan and <i>panchangabada</i> in elevation.</li></ul>						
10. Construction Technology							
Structural System Building Techniques Material of Construction	<ul> <li>Rekha vimana and pidha jagamohana of Kalingan order.</li> <li>Ashlar dry Masonry</li> <li>Laterite is used for the foundation structure and the compound wall and khandolite is used for antarala and the façade of the jagamohana.</li> </ul>						
11. Condition Assessment							
In General	Good / Fair : Fair. Sign of Deterioration						

			Dang	er of Di	sappe	arance				
In Brief (Attac	ch extra sheet	if neces	sary):							
	getations like water in the gar							ll of the	e templ	e and
12. Threats to	the Property									
Natural Negligence Vandalism Urban Pressures										
X x	x x	Х	x	x	x	Х	х	Х	x	Х
SECTION III: REFERENCES										
Reference Sources (published and unpublished textual details)  14. Photographs: 10 nos										
·····			(attac	h list as	in pag	ge 6, in	case of	multiple	e photo	graphs)
Photo Referer CAPTION	:									
15. Audio / Vi	deo									
Reference DESCRIPTIOI	N	:		(rel	ated to	o rituals	/ perto	rmance	/ festiva	als etc.)
16. Maps/Plar	ns/Drawings									
17. Listers										
NAME :	J.S.Naik.		NAME :							
18.Reviewers										
NAME : COMMENTS	Dr. S. Pradha	n		NAME : COMME	NTS :					

Serious Deterioration