

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: 0R/PRI- 05 **SECTION I: IDENTIFICATION** 1. Name Kuntesvara Temple, Aragada, Dist. - Puri Present Past Other Name (if any): 2. Location **LONGITUDE** 85⁰ 43' 15" E 20⁰ 07' 02" N LATITUDE **ELEVATION** 12 ft Address : Village (village code) Aragada Post: Godiput Matiapada Via: Jatani Tehsil: Pipili District: Puri State: Orissa PIN: 752050 : The temple is located on the right bank of the river Daya Approach and very close to the South-Eastern Railway bridge and about 7 kms from Jatani. 3. Property Type Other Structures **Buildings** Religious structures Temple Wall Palace Fort Mosque Gateway Citadel Pillar Minar Govt. building Church Others (specify) Railway station Monastery Defense building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Engineering structure Open space and related Note: structures The temple has a rekha vimana Bridge Public square and pidha jagamohana of Kalingan order. Tunnel Park or garden Other engineering structure Graveyard Baolis, Well Tank Cave

4. Property Use ABANDONED / IN USE: In use Present Living temple, the presiding deity is a patalaphuta Sivalinga within a circular yonipitha made of black chlorite which is 0.65 mtrs below the entrance level. **Past** Worshipped 5. Age (Source) PERIOD Somavamsi rule 10th-11th centuries A.D. YEARS Last quarter of the 10th century A.D. or early part of the Precise date of Construction 11th century A.D. Completion Subsequent changes Renovated by and conserved Orissa State Archaeology. **Destruction / Demolition** 6. Ownership / Level of Protection SINGLE /MULTIPLE : Multiple **Public**: Archaeological Survey of: Protected Monument of Orissa State Archaeology / State Archaeology Department / Any Other (Please specify) **Private** Any other (Please specify) Endowment Department, Government of Orissa. Name **Address** Orissa State Archaeology, Paryatan Bhawan, B.J.B. Nagar, Bhubaneswar, Orissa. 0674-2432147 Phone 7. Association WITH EVENTS In History In Rituals Kartika Purnima, Sivaratri, etc are held here. In Building Construction Any other (specify) WITH PERSONS Patron Now the Orissa State Archaeology Architect / Engineer Any other (specify) Endowment Department, Government of Orissa. 8. Statement of Significance Architectural Architectural Archaeological Archaeological Historical Religious Religious Any other (specify) On the basis of iconographical feature of the Parsvadevata

SECTION II: DESCRIPTION

A.D.

images, the temple can be dated to the 10th - 11th centuries

9. Physical Description and De	corative Features						
 Context Urban / Rural Setting Surroundings 	* Drawings (Attach extra sheet if necessary): No Rural setting						
ŭ	Stand in isolation Complex Integral part of a landscape / Street / Complex :						
 Quantification 							
Area Dimension (LxBxH)	: 12.26 mtrs x 6.25 mtrs x about 13.00 mtrs (m / cm/ feet / inch)						
Number of Blocks	: Two						
Number of Storys	:						
• Spatial Organization Orientation Plan	Facing towards east.It has a square <i>vimana</i> and rectangular <i>jagamohana</i> and an <i>antarala</i> in between them.						
Allocation of Spaces	 28.30 mtrs x 24.15 mtrs in length and breadth respectively. 						
• Ornamentation							
Exteriors	Devoid of decorations except the <i>dopichhasimha</i> and <i>deulacharini</i> s over the <i>beki</i> to support the <i>amlakasila</i> and <i>udyotasimha</i> in all <i>raha</i> .						
Interiors	: Plain						
Movable Collections	Images of Mahisasuramardini Durga, Ganesa, Umamahesvara, Kuvera, <i>udyotasimha</i> and architectural members.						
* Any Other (specify)	 The temple is pancharatha on plan and panchangabada in elevation. 						
10. Construction Technology							
Structural System Building Techniques Material of Construction 11. Condition Assessment	 Rekha vimana and pidha jagamohana of Kalingan order. Ashlar dry masonry. Khandolite stone is used for the construction of the temple and latarite for the compound wall. 						
In General	Good / Fair : Good Sign of Deterioration Serious Deterioration Danger of Disappearance						

In Brief (Attach extra sheet if necessary)

The temple is in a good state of preservation, however, pipal tree and creepers are noticed in the roof of the *vimana* and *jagamohana*.

12. Threats t	o the Pro	perty									
			√	Natur Neglio Vanda Urbar	gence	ıres					
X x	x	x	X	x	X	X	х	x	x	x	x
			<u>SECT</u>	ION III	: REFE	RENC	CES				
13. Reference	Sources	(publisł	ned an	d unpul	olished	textual	details)			
1. B.K Ratha	a, 1996, <i>Th</i>	e Forg	otten N	Мопите	ents of C	Drissa,	Vol 3	, New [Delhi.		
14. Photograp	ohs: 07 no	S									
<u> </u>				(Attach	n list as	in page	e 6, in d	case of	multipl	e phot	ographs)
Photo Referen	ce		:								
15. Audio / Vi	deo										
					(Rela	ated to	rituals	/ perfor	mance	/ festi	vals etc.)
Reference DESCRIPTION	N		:								
16. Maps/Plar	ns/Drawing	gs									
17. Listers											
NAME :	Jaya Sh	ıankar I	Naik	NA	ME :						
18.Reviewers											
NAME : COMMENTS	Dr. S Pra	dhan.			AME :	NTS :					