

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: 0R/PRI- 44

SECTION I : IDENTIFICATION 1. Name							
Present Past Other Name (if any): 2. Location	: Markandesvara Siva Ter : :	mple, Puri Town, Dist Puri					
LONGITUDE 85 ⁰ 49 ['] 94 ["] E	LATITUDE 19 ⁰ 48 ['] 62 ["] N	ELEVATION 16 ft					
Address	: Village (village code) Post : Puri Tehsil: Puri State : Orissa	Upara Markandesvara Sahi, Via: Puri District: Puri PIN: 752001					
Approach	: The temple is located on the southern embankment of Markandesvara tank which can be approached on the right side of Markandesvara road leading from Markandesvara chowk to Prui-Brahmagiri road.						
3. Property Type							
Buildings Palace Fort Citadel Govt. building Railway station Defense building Industrial building Other public building Residential building	Religious structures Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum	Other Structures Wall Gateway Pillar Others (specify)					
Engineering structure Bridge Tunnel Other engineering structure	structures If Public square ir Park or garden o	Note: It is a Kalingan style of temple In which the vimana is of rekha Inder & the jagamohana is of Inidia order.					

4. Property Use		
		ABANDONED / IN USE: In use
Present	:	Living temple, the presiding deity is a Sivalinga within
		a circular Yonipitha.
Past	:	Worshipped.
5. Age (Source)		
PERIOD		Canga rulo
YEARS	:	Ganga rule 12 th century A.D.
Precise date of Construction	:	12 th century A.D.
Completion	:	12 th century A.D.
Subsequent changes	:	The Natamandira and Bhogamandira are later addition
Destruction / Demolition		to the temple.
Destruction / Demolition	•	
6. Ownership / Level of Protection	<u>n</u>	
		SINGLE /MULTIPLE : Single
Public: Archaeological Survey of	:	Forders and Development Ocat of Original
India / State Archaeology Department / Any Other (Please		Endowment Department, Govt. of Orissa.
specify)		
Private	:	
Any other (Please specify)	:	The temple is looked after by the priest
Name	:	Narasingha Tiadi
Address	:	Upara Markandesvara Sahi, Puri
Phone 7. Association	:	
7. Association		
WITH EVENTS		
In History	:	According to local tradition the temple was built by the Gangas.
In Rituals	:	Sitalsasthi, Janmastami, Risi Panchami, Rakhi
		Purnima, Sivaratri, Sankranti, Narasimha Chaturdasi
In Building Construction		etc. observed.
In Building Construction Any other (specify)	•	Marriage & thread ceremony practiced here.
WITH PERSONS	•	marriage a timeda ceremony practiced here.
Patron	:	Originally the Gangas, but now the Endowment
		Department, Govt. of Orissa is looked after the temple.
Architect / Engineer	:	
Any other (specify)	:	
8. Statement of Significance		
Architectural		Architectural
Archaeological		Archaeological
Historical Religious	✓	Historical Religious
Any other (specify)	:	On the basis of architectural features the temple can be
		assigned to the early part of the Ganga rule i.e. 12 th century AD.

SECTION II: DESCRIPTION

 Context Urban / Rural Setting Surroundings 	:	* Drawings (Attach extra sheet if necessary):No Urban setting					
Carrounanigo		Stand in isolation/ Complex Integral part of a landscape / Street / Complex :					
Quantification		40.70					
Area Dimension (LxBxH)	:	19.76 mtrs x 9.60 mtrs x 8.00mtrs(approximate height) (m / cm/ feet / inch)					
Number of Blocks Number of Storys	:	Four					
 Spatial Organization 							
Orientation	:	Facing towards east.					
Plan	:	The temple has a square <i>vimana</i> and <i>jagamohana</i> stands on a lofty platform (19.76 mtrs x 9.60 mtrs x 1.30 mtrs) and both the <i>Natamandira</i> and <i>Bhogamandira</i> are later additions, which also stand on a shallow platform.					
Allocation of Spaces	:	30.00 mtrs(L) x 22.00 mtrs.(B)					
ARCHITECTURAL STYLE • Ornamentation							
Exteriors	:	Decorated with secular images like <i>nyikas, mithunas</i> and erotics in the upper <i>jangha, Vidala</i> motifs like <i>Gagavyala</i> and <i>Vidala</i> in the <i>tala jangha</i> . The rest portions of the <i>bada</i> and <i>gandi</i> are devoid of any decorations.					
Interiors	:	Plain					
Movable Collections	:	Nil					
* Any Other (specify)	:	The temple is <i>pancharatha</i> on plan and has <i>panchanga bada</i> in elevation.					
10. Construction Technology							
Structural System	:	Kalingan style of architecture in which the vimana is a rekha deula and jagamohana is a pidha deula. Both the bhogamandapa and natamandira have pidha roof.					
Building Techniques		Ashlar masonry.					
Material of Construction	:	Grey sandstone is used for the temple construction and laterite for the foundation and the compound wall.					
11. Condition Assessment							
In General	G	ood / Fair :					
	√	Sign of Deterioration					
	-	-					
		Serious Deterioration					

In Brief	(Attach	extra	sheet	if	necessary	1)):
----------	---------	-------	-------	----	-----------	----	----

The temple is located 5.50 mtrs below the present road level which stagnants the rain water and a crack is noticed on the *mastaka* due to the presence of a big pipal tree.

12. Threats to	the Prope	erty								
		-	Neç Var	tural gligence ndalism pan Pres	sures					
X x	х	x x	X	Х	х	х	Х	X	х	X
		SE	CTION	III: REF	EREN	CES				
13. Reference	Sources (published	and unp	oublished	d textua	l details	s)			
14. Photograp	hs									
			(Atta	ach list a	s in pag	ge 6, in	case of	multiple	e photo	graphs)
Photo Referen CAPTION	ce		: :							
15. Audio / Vi	deo									
				(Rel	ated to	rituals,	/ perfor	mance,	/ festiv	als etc.)
Reference DESCRIPTION	N		: :							
16. Maps/Plan	s/Drawing	ıs								
17. Listers										
NAME :	J. S. Naik			NAME	:					
18.Reviewers										
NAME : COMMENTS	Dr. S. Pra	dhan		NAME COMM						