

## INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

## **Documentation format for Archaeological / Heritage Sites / Monuments**

Serial No.: 0R/PRI- 1		
1. Name	SECTION I: IDENTIFICATION	ON
Present Past Other Name (if any):	: Nilakantesvara Siva 1 : :	Геmple, Bhimapur, Dist Puri
2. Location		
<b>LONGITUDE</b> 85 <sup>0</sup> 44' 54" E	<b>LATITUDE</b> 19 <sup>0</sup> 58' 48" N	N <b>ELEVATION</b> 10 ft
Address	: Village (village code Post:Bhimapur Tehsil: Satyabadi State : Orissa	P) Bhimapur Via: Satyabadi. District: Puri PIN: 752014
Approach	which leading from about 9 km. from Sal	ed in the right side of the road Sakhigopala to Banpur and is khigopala and 7 km.from Banpur. umaresvara temple,Indipur.
3. Property Type		
Buildings  Palace Fort Citadel Govt. building Railway station Defense building Industrial building Other public building Residential building	Religious structures  Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum	Other Structures  Wall Gateway Pillar Others (specify)
Engineering structure  Bridge Tunnel Other engineering structure	Open space and related structures Public square Park or garden Graveyard Baolis, Well Tank Cave	<b>Note:</b> The temple has a <i>vimana</i> , <i>jagamohana</i> and <i>bhogamandapa</i> . It is a <i>pidha</i> temple of <i>Kalingan</i> order.

4. Property Use ABANDONED / IN USE: In use **Present** It is a living temple enshrines a chlorite Sivalinga within a circular yonipitha made of khandolite. **Past** Worshipped. 5. Age (Source) PERIOD British period. YEARS 19<sup>th</sup> century A.D. 19<sup>th</sup> century A.D. Precise date of Construction Completion Subsequent changes **Destruction / Demolition** 6. Ownership / Level of Protection SINGLE /MULTIPLE: Multiple. **Public**: Archaeological Survey of : Nilakantesvara Temple Committee. State Archaeology / Department / Any Other (Please specify) Private Any other (Please specify) Under the cares and maintenance of Gandhi Ratha, president of Nilakantesvara Temple Committee. Name At/P.o.-Bhimapur, Dist.-Puri, Orissa. Pin-752014. Address Phone 7. Association WITH EVENTS In History In Rituals Jagara jatra, Pana sankrati, Sitalasathi etc. In Building Construction Any other (specify) WITH PERSONS **Patron** Nilakantesvara Temple Committee. **Architect / Engineer** Any other (specify) 8. Statement of Significance ✓ Architectural. Architectural Archaeological ✓ Archaeological.

Any other (specify) : On the basis of architectural features and the iconography of detached sculpture(Ganesa)the temple can be assigned to

19<sup>th</sup> century A.D.

Historical Religious

## **SECTION II: DESCRIPTION**

9. Physical Description and Decorative Features			
<ul> <li>Context</li> <li>Urban / Rural Setting</li> <li>Surroundings</li> </ul>	* <b>Drawings</b> (Attach extra sheet if necessary):No Rural setting		
Curroundings	Stand in isolation Street. Integral part of a landscape / Street / Complex :		
• Quantification Area Dimension (LxBxH)	: 12.95mtrs. x 8.95mtrs. x 7.00mtrs.(approximate.) ( <b>m</b> / cm/ feet / inch)		
Number of Blocks Number of Storys	: Three. :		
• Spatial Organization Orientation Plan	<ul> <li>The temple is facing towards east.</li> <li>Consists of a square <i>vimana</i>, a square <i>jagamohana</i> and a rectangular <i>bhogamandapa</i> having an <i>antarala</i> in between them which stands over a <i>pista</i>.</li> </ul>		
Allocation of Spaces	: 13.00mtrs.x 9.00mtrs. length and breadth respectively.		
• Ornamentation Exteriors Interiors Movable Collections	<ul> <li>It is decorated with stucco figures of elephant, lion, lotus, sampati demon face with knife in two hands.</li> <li>Plain</li> <li>Four armed Ganesa.</li> </ul>		
* Any Other (specify)	: The vimana is pancharatha on plan and panchangabada in elevation, jagamohana is triratha on plan and panchangabada in elevation and the bhogamandapa is panchangabada in elevation.		
10. Construction Technology			
Structural System  Building Techniques	<ul><li>The <i>vimana</i>, <i>jagamohana</i> and <i>bhogamandapa</i> are of <i>pidha</i> style of <i>Kalingan</i> order.</li><li>Ashlar Masonry</li></ul>		
Material of Construction	: Laterite is used for the construction of the temple where as the platform is made of khandolites. A thick coat of lime plaster is given over the laterite structure.		
11. Condition Assessment			
In General	Good / Fair : Fair.		
	Sign of Deterioration Serious Deterioration Danger of Disappearance		
In Brief (Attach extra sheet if necessary):			

Wild vegetations, moss, lichen and creepers are grown over the surface of temple.

12. Threats to	the Property			
		Natural Negligence Vandalism Urban Pressures		
X	x x x	X X X X X X X X X X SECTION III: REFERENCES		
13. Reference Sources (published and unpublished textual details)				
	XI.	,		
14. Photograp	ohs: 05 nos			
		(Attach list as in page 6, in case of multiple photographs)		
Photo Referen	ce	: :		
15. Audio / Vi	deo			
		(Related to rituals / performance / festivals etc.)		
Reference DESCRIPTION	N	: :		
16. Maps/Plar	ns/Drawings			
_				
17. Listers				
NAME :	A.R.Sahoo.	NAME :		
18.Reviewers				
NAME : COMMENTS	Dr. S. Pradhan	NAME : COMMENTS :		