

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: 0R/PRI- 47

SECTION I: IDENTIFICATION				
1. Name				
Present Past Other Name (if any): 2. Location	: Nilakanthesvara temple : :	e, Kanti, Dist. Puri		
LONGITUDE 85 ⁰ 46' 10" E	LATITUDE 20 ⁰ 08' 09" N	ELEVATION 30 ft		
Address	: Village (village code) Post : Kanti Tehsil: Pipili State : Orissa	Kanti Via: Pipili District: Puri PIN: 752104		
Approach	the right side of the roa	bank of the river Daya and on ad leading from Jatani to Pipili. It from Pipili and 5 km from Jatani.		
3. Property Type				
Buildings Palace Fort Citadel Govt. building Railway station Defense building Industrial building Other public buildings	Religious structures Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum	Other Structures Wall Gateway Pillar Others (specify):		
Residential building Engineering structure Bridge Tunnel Other engineering structure	Open space and related structures Public square Park or garden Graveyard Baolis, Well Tank Cave	The temple has a rekha vimana of Kalingan order. Recently a concrete mandapa is added to the vimana and which act as the jagamohana now. The temple is entirely plastered with lime but on the basis of architectural features it can be dated to the 16 th century A.D.		

4. Property Use		
	ABANDONED / IN USE: Abandoned	
Present	: It is a living temple and the presiding deity is a patalaphuta Siva lingam within a circular yonipitha.	
Past	: Worshipped.	
5. Age (Source)		
PERIOD YEARS Precise date of Construction Completion Subsequent changes Destruction / Demolition 6. Ownership / Level of Protection	 Suryavamsi Gajapati rule 16th century A.D. 16th century A.D. In 2006 the R. C.C <i>mandapa</i> in front of the temple and the plastering work of the temple is done. 	
•		
Public: Archaeological Survey of India / State Archaeology Department / Any Other (Please specify) Private Any other (Please specify)	: : Raghunatha temple committee under the president	
Name Address Phone 7. Association	 ship of Gunanidhi Barala. : Gunanidhi Barala : At/Po- Kanti, Dist- Puri, Pin-752104, Orissa. : 	
WITH EVENTS In History In Rituals In Building Construction Any other (specify) WITH PERSONS Patron	 : : Sivaratri, , Kartikapurnima etc. : : Thread ceremony, engagement, marriages are held here. : Originally, the Suryavamsi Gajapati but now the Arjunesvara temple committee. 	
Architect / Engineer Any other (specify)	: :	
8. Statement of Significance		
Architectural Archaeological Historical Religious Any other (specify)	 Architectural Archaeological On architectural and sculptural ground the temple can be dated to the 16th century A.D. 	

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features				
• Context Urban / Rural Setting : Surroundings	* Drawings (Attach extra sheet if necessary) : No Rural settir			
Cancanango	Stand in isolation Integral part of a landscape / Street / Complex :	Stand in isolation		
 Quantification 				
Area Dimension (L x B x H) :	03.55 mtrs x 3.55 mtrs x (approxin	nately 9.00 mtrs.) (m / cm/ feet / inch)		
Number of Blocks :	Two	(1117 01111 10007 111011)		
Number of Storys :				
Spatial Organization Orientation	Cosing towards and			
Orientation : Plan :	Facing towards east The <i>vimana</i> is square on plan and	the flat mandana is		
riali .	rectangular on plan.	u tile ilat manuapa is		
Allocation of Spaces :	45.00 mtrs x32.10 mtrs in length a respectively.	nd breadth		
• Ornamentation				
Exteriors :	plain Plain			
Interiors : Movable Collections :	A broken image of Visnu is kept be	ehind the temple		
* Any Other (specify)	The temple is <i>pancharatha</i> on plain elevation.	-		
10. Construction Technology				
Structural System :	Rekha vimana of Kalingan order.			
Building Techniques	Ashlars masonry			
Material of Construction :	Laterite.			
11. Condition Assessment				
In General Good / Fair :	Good			
Sign of Deterioration Serious Deterioration Danger of Disappearance				
In Brief (Attach extra sheet if neces	ssary):			
The temple is in a good state of prese	ervation .			

12. Threats to the Property

		✓ Natural Negligence Vandalism Urban Pressures
x x x x x x x	< x x x x x x x x x	x x x x x x x x x x x x x x x x x x x
	<u>s</u>	SECTION III: REFERENCES
13. Reference	Sources (publishe	ed and unpublished textual details)
1. B. K Rath 2.	n, 1996, The forgott	en monuments of Orissa, vol3, New Delhi.
14. Photograp	phs: 05 nos	
<u> </u>		(Attach list as in page 6, in case of multiple photographs)
Photo Refere	nce	: :
15. Audio / Vi	deo	
		(Related to rituals / performance / festivals etc.)
Reference DESCRIPTION	N	: :
16. Maps/Plar	ns/Drawings	
17. Listers		
NAME :	J.S Nayak	NAME:
18. Reviewers	S	
NAME: COMMENTS	Dr. S. Pradhan	NAME: COMMENTS: