

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: 0R/PRI- 28

SECTION I: IDENTIFICATION								
1. Name								
Present Past Other Name (if any): 2. Location	Radhakanta Temple, Gada Begunia Pada.Gopinath Temple							
LONGITUDE 85 ⁰ 42' 11" E	LATITUDE 20 ⁰ 04' 02" N	ELEVATION 26 ft						
Address	: Village (village code) Post:Ghoradia Tehsil: Pipili State: Orissa	Via:Delang District: Puri PIN: 752015						
Approach 3. Property Type	: The temple is located on the left bank of the river Daya and situated on the right of Khurda-Pattanayikia road and 14km. from Khurda town.							
	Dell'ade and administration of	Other Other Comme						
Palace Fort Citadel Govt. building Railway station Defense building Industrial building Other public building Residential building	Religious structures Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum	Other Structures Wall Gateway Pillar Others (specify)						
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structures Public square Park or garden Graveyard Baolis, Well Tank Cave	Note: Both the <i>vimana</i> and jagamohana are of <i>pidha</i> style of <i>Kalingan</i> order.						

4. Property Use ABANDONED / IN USE: In use **Present** Living temple, the presiding deity is an image of Krisna made of black-chlorite and Radha made of Asthadhatu placed on a moulded high pedestal. Worshipped. **Past** 5. Age (Source) **PERIOD** British Period/Bhoi dynasty of Khurda. 18th century A.D. **YEARS** 18th century A.D. **Precise date of Construction** Completion Subsequent changes **Destruction / Demolition** 6. Ownership / Level of Protection SINGLE /MULTIPLE : Single. **Public**: Archaeological Survey of : State Archaeology / Department / Any Other (Please specify) Private Any other (Please specify) Under the care and maintenance of Zamindar Nilambara Harichandana Mohapatra. Name Address At-GadaBeguniaPada., Po-Ghoradia, Dist-Puri, Orissa-752015. Phone 7. Association WITH EVENTS In History In Rituals Janamasthami, Radhasthami, Dolapurnima, Ramanavami etc. observed here. In Building Construction Any other (specify) Engagements held here. • WITH PERSONS Patron ---Architect / Engineer Any other (specify) Nilambar Harichandana Mahapatra (Local zamindar)

8. Statement of Significance

Architectural ✓ Architectural.

Archaeological ✓ Archaeological.

Historical Religious

Any other (specify) : On the basis of sculptural ground the temple can be

assigned to the 18th century A.D.

SECTION II: DESCRIPTION

9. Physical Description and De	corative Features
 Context Urban / Rural Setting Surroundings 	* Drawings (Attach extra sheet if necessary):No : Rural setting
	Stand in isolation Street. Integral part of a landscape / Street / Complex :
• Quantification Area Dimension (L x B x H)	: 10.45mtrs.x 5.48mtrs. x 7.00mtrs(approximate height) (m / cm/ feet / inch)
Number of Blocks Number of Storys	: Two :
Spatial Organization Orientation Plan Allocation of Spaces	 The temple is facing towards east. Consists of a square <i>vimana</i> and a <i>jagamohana</i> joined by an <i>antarala</i> that stands over a low <i>pista</i>. 40mtrs x 16.00mtrs.in length and breadth respectively.
• Ornamentation Exteriors Interiors Movable Collections * Any Other (specify)	 Devoid of decorations except erotic sculptures in stucco carved out in the <i>bada</i> of the <i>vimana</i>. Plain Nil. The <i>vimana</i> is <i>pancharatha</i> on plan and both the <i>vimana</i> and <i>jagamohana</i> are <i>panchangabada</i> in elevation.
10. Construction Technology	
Structural System Building Techniques Material of Construction	 Both the <i>vimana</i> and <i>jagamohana</i> are of <i>pidha</i> order of impoverished <i>Kalingan</i> style. Ashlar Masonry Laterite is used for the foundation, structure and the compound wall.
11. Condition Assessment	
In General	Good / Fair : Good. Sign of Deterioration Serious Deterioration Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Due to the proper care and maintenance the temple is in a good state of preservation. **12. Threats to the Property**

		,	Natura Neglige Vanda Urban	ence	S				
X	x x		X X SECTION	III: XEF	× ERENC	× ES	x	x	х
13. Referenc	e Sources (pub	olished a	and unpub	lished tex	tual deta	ails)			
14. Photogra	phs: 12 nos								
			(Attach	list as in p	page 6, i	n case	e of mul	ltiple ph	notographs)
Photo Refere	nce	:							
15. Audio / V	ideo								
				(Relate	d to ritua	als / pe	rforma	nce / fe	stivals etc.)
Reference DESCRIPTIO	N	:							
16. Maps/Pla	ns/Drawings								
17. Listers									
NAME :	J.S.Naik.		NAI	ИE :					
18.Reviewers	S								
NAME : COMMENTS	Dr. S. Pradha	n		AME : DMMENT:	S:				