

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: 0R/PRI-77

SECTION I : IDENTIFICATION 1. Name						
Present Past Other Name (if any):	: Siddha Mahavira Templ : Kumuda Mahavira :	e,Puri Town, Dist Puri				
LONGITUDE 85 ⁰ 50 ['] 86 ^{''} E	LATITUDE 19 ⁰ 49 ¹ 14 ¹ N	ELEVATION 60 ft				
Address	: Village (village code) Post : Puri Tehsil: Puri State : Orissa	Siddha Mahavira Patna Via: Puri District: Puri PIN: 752001				
Approach 3. Property Type	the north eastern out approached on the rigl	the Siddha Mahavira Patna, in tskirt of Puri which can be ht side of the road branching road near the railway label				
Buildings Palace Fort Citadel Govt. building Railway station Defense building Industrial building Other public building Residential building	Religious structures Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum	Other Structures Wall Gateway Pillar Others (specify)				
Engineering structure Bridge Tunnel Other engineering structure	structures Public square	Note: Impoverished <i>Kalingan</i> order in which both the <i>vimana</i> and iagamohana are of pidha style.				

4. Property Use ABANDONED / IN USE: In use **Present** Living temple, the presiding deity is Veer Hanuman, one of the most beautiful & largest image in Orissa. **Past** Worshipped. 5. Age (Source) **PERIOD** Suryavamsi Rule 15th – 16th centuries A.D. YEARS Precise date of Construction Completion Subsequent changes **Destruction / Demolition** 6. Ownership / Level of Protection SINGLE /MULTIPLE: Multiple **Public**: Archaeological Survey of : State Archaeology Endowment Department, Govt. of Orissa. Department / Any Other (Please specify) Siddha Mahavira Trust Board **Private** Any other (Please specify) Bibhudananda Mishra (Chief Priest) Name **Address** Siddha Mahavira Patna, Puri Phone 7. Association WITH EVENTS In History Locals ascribe the temple of Prataparudra deva of Ganga dynasty. In Rituals Hanuman Jayanti, Ram Navami, Panasankranti etc. are observed. In Building Construction Any other (specify) Thread ceremony, engagement etc. WITH PERSONS **Patron** Originally the Survayamsi Gajapati, but now by the Endowment Department, Govt. of Orissa. Architect / Engineer Any other (specify) 8. Statement of Significance Architectural Archaeological

Any other (specify) : Sculptural fragments & architectural fragments of earlier temples are used in the walls and niches of the present

temple.

Historical Religious

SECTION II: DESCRIPTION

9. Physical Description and Dec	Oral						
 Context Urban / Rural Setting Surroundings 	:	* Drawings (Attach extra sheet if necessary):No Urban setting					
		Stand in isolation Complex Integral part of a landscape / Street / Complex :					
 Quantification 							
Area Dimension (LxBxH)	:	11.25 mtrs x 11.05 mtrs x 8.78 mtrs (m / cm/ feet / inch					
Number of Blocks		Two					
Number of Storys	:						
Spatial Organization							
Orientation	:	The temple is facing towards east					
Plan	:	The temple has a <i>vimana</i> and a <i>jagamaohana</i> stands on a rectangular platform measuring 1.12 mtrs in height					
Allocation of Spaces	:	height. 12.35mtrs x 11.50 mtrs (platform)					
ARCHITECTURAL STYLE • Ornamentation							
Exteriors	:	Though the <i>bada</i> of <i>jagamohana</i> is plain but some of the beautiful sculptures of earlier temples are inserted which illustrate the technique of temple building – how the stones are carried by elephants, how the block of stones were lifted to the temples through an wooder ramp etc.					
Interiors	:	Plain					
Movable Collections * Any Other (specify)	:	Nil The <i>vimana</i> is <i>pancharatna</i> on plan and					
	•	panchangabada in elevation.					
10. Construction Technology							
Structural System	:	Both <i>vimana</i> and <i>jagamohana</i> are of <i>pidha</i> style which is a departure from the <i>Kalingan</i> order temple.					
Building Techniques	:	Ashlar dry masonry					
Material of Construction	:	Laterite is used both for the temple construction and the foundation. Burned brick is used for the compound wall.					
11. Condition Assessment		wan.					
In General	Good / Fair : Good						
	✓	Sign of Deterioration					
		Serious Deterioration					
In Duint (Attack control of a set if a se		Danger of Disappearance					

In Brief (Attach extra sheet if necessary):

Due to proper care and maintenance by the Siddha Mahavira Trust Board the temple is in a

fair condition.

12. Inreats to	tne Property											
		✓	Natural Neglige Vandal Urban	ence ism	res							
X x	x x	X	X	x	x	х	х	x	х	х		
SECTION III: REFERENCES												
13. Reference Sources (published and unpublished textual details)												
14. Photograp	ohs											
			(Attach	list as i	n page	6, in	case of	multiple	e photo	graphs)		
Photo Referent CAPTION	ice	: :										
15. Audio / Vi	deo											
				(Relate	ed to ri	tuals,	/ perfor	mance,	/ festiva	als etc.)		
Reference DESCRIPTION	N	:										
16. Maps/Plar	ns/Drawings											
17. Listers												
NAME :	J. S. Naik		N.	AME :								
18. Reviewers	5											
NAME : COMMENTS	Dr. S. Pradhan			ME : MMEN	ITS :							