

4. Property Use

## INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

## **Documentation format for Archaeological / Heritage Sites / Monuments**

Serial No.: 0R / PRI- 38 **SECTION I: IDENTIFICATION** 1. Name Siva Temple (South east corner of the Somanath Present temple), Ghoradia, Dist.- Puri. **Past** Other Name (if any): 2. Location **LONGITUDE** 85<sup>0</sup>44'12"E 20<sup>0</sup>04'40" N LATITUDE **ELEVATION** 22 ft. Address Village (village code) Ghoradia Post: Delang Via: Delang Tehsil: Puri District: Puri PIN: 7522015 State: Orissa The temple is located on the left bank of the river Daya Approach and in the precinct of Somanath temple at Ghoradia. It is situated on the right side of the Khurda-Patnayikia road and about 2 Km from the road either branching at Gada Begunia Pada or Kuapada Chowk. It is 20 Km from Khurda town. 3. Property Type **Buildings** Religious structures Other Structures Temple Wall Palace Fort Mosque Gateway Citadel Minar Pillar Govt. building Others (specify) Church Railway station Monastery Defense building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Engineering structure Open space and related Note: structures The temple has a rekha Bridge Public square vimana of Kalingan order. It is Park or garden Tunnel one of the subsidiary shrines of Other engineering structure Graveyard the panchayatana temple. Baolis, Well Tank Cave

	ABANDONED / IN USE: Abandoned			
Present Past	<ul><li>Non-living temple, the presiding deity is missing now.</li><li>Worshipped</li></ul>			
5. Age (Source)				
PERIOD YEARS Precise date of Construction Completion Subsequent changes Destruction / Demolition	<ul> <li>Late Somavamsi Rule</li> <li>11<sup>th</sup> century A.D.</li> <li>11<sup>th</sup> century A.D.</li> <li></li> <li>Renovated and conserved by Orissa State Archaeology.</li> <li></li> </ul>			
6. Ownership / Level of Protection	on			
·	SINGLE /MULTIPLE : Multiple			
Public: Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)	: Protected monument of Orissa State Archaeology			
Private Any other (Please specify) Name Address Phone	<ul> <li>:</li> <li>: Somanath Temple Committee</li> <li>: Orissa State Archaeology</li> <li>: Paryatan Bhavan, BJB Nagar, Bhubaneswar, Orissa</li> <li>: 0674-2432147</li> </ul>			
7. Association				
WITH EVENTS In History In Rituals In Building Construction Any other (specify)     WITH PERSONS Patron	: : : : Originally the Somavamsi, but now the Orissa State			
Architect / Engineer Any other (specify)	Archaeology. : :			
8. Statement of Significance				
Architectural Archaeological Historical Religious Any other (specify)	<ul> <li>∴ Architectural</li> <li>∴</li> <li>∴</li></ul>			

## **SECTION II: DESCRIPTION**

• Context		* Drawings (Attach extra sheet if ned	cessarv) : No
Urban / Rural Setting Surroundings	:	Drawings ( maon oxula onlock ii noc	Rural setting
<b>3</b>		Stand in isolation Integral part of a landscape / Street / Complex :	Complex
<ul> <li>Quantification</li> </ul>			
Area Dimension ( L x B x H)	:	3.00 mtrs. X 2.82 mtrs. X 5.50 mtrs.	/ //ft/:
Number of Blocks		one	(m / cm/ feet / inch
Number of Storys	:	NA	
Spatial Organization			
Orientation	:	Facing towards west.	
Plan	:	Consists of a square <i>vimana</i>	ad broadth
Allocation of Spaces	•	20.50 Mtrs x 17.015 mtrs in length ar respectively	iu breaum
ARCHITECTURAL STYLE			
<ul> <li>Ornamentation</li> <li>Exteriors</li> </ul>		Descrated with vairamundi niches in	the ienahe ministur
Exteriors	•	Decorated with <i>vajramundi</i> niches in <i>rekhamundis</i> in all <i>pagas</i> at the <i>talagarbhika</i> below the <i>parsvadevata</i> tier <i>pidha</i> surmounted by a <i>rekhamu</i> above the frontal <i>raha</i> .	base of the gand a niches and a three
Interiors	:	Plain	
Movable Collections	:	It includes sculptures such as Ganes Liga worship, Nandi, Herostone etc.	a,Surya, hanuman
* Any Other (specify)	:	The temple is <i>pancharatha</i> on plan elevation.	and <i>triangabada</i> ii
10. Construction Technology			
Structural System	:	Rekaha vimana of Kalingan order.	
<b>Building Techniques</b>	:	Ashlar dry masonry	
Material of Construction	:	Khandolite used for the temple conslaterite for the foundation and the con	
11. Condition Assessment			
In General Good / Fair	:	Fair	
Sign of Deterioration			
Serious Deterioration			
Danger of Disappearance			
In Brief (Attach extra sheet if ne	cess	sary):	

Bird excreta in the temple are r	major problem for concern.
12. Threats to the Property	
x x x x x x x x x x x x x	Natural Negligence Vandalism Urban Pressures  X X X X X X X X X X X X X X X X X X X
	SECTION III: REFERENCES
13. Reference Sources (publis	shed and unpublished textual details)
•	rchaeology in Orissa, Vol. I, New Delhi. Indu Temple Art of Orissa, Vol. I, Leiden.
14. Filotographs. 00 hos	(Attach list as in page 6, in case of multiple photographs
Photo Reference CAPTION	: :
15. Audio / Video	
	(Related to rituals / performance / festivals etc.)
Reference DESCRIPTION	: :
16. Maps/Plans/Drawings	
17. Listers	

NAME:

NAME:

COMMENTS:

NAME: J. S. Naik

Dr. S. Pradhan

18. Reviewers

COMMENTS

NAME: