

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: 0R / PRI - 58

SECTION I: IDENTIFICATION 1. Name Present Trivenisvara Temple, Madhipur, Dist.- Puri Past Other Name (if any): 2. Location **LONGITUDE** 86⁰ 05' 30" E 19⁰ 53' 45" N LATITUDE **ELEVATION** 22 ft Address Village (village code) Madhipur Post: Konarka Via: Konarka Tehsil: Konarka District: Puri State: Orissa **PIN**: 752111 Approach The temple is located on the left side of the Bhubaneswar-Konarka road branching at Damodara Girls High School chowk near the Konarka police station. It is about 2.5 km north-west of Sun temple Konarka. 3. Property Type **Buildings** Religious structures Other Structures Palace Temple Wall Fort Mosque Gateway Citadel Minar Pillar Govt. building Church Others (specify): Monastery Railway station Defense building Stupa Industrial building Tomb, Mausoleum Other public buildings Note: Residential building The temple has rekha vimana of Kalingan order. Local people Engineering structure Open space and related renovated the temple cement structures plaster, so its originally artistic Bridge Public square beauty is now concealed. Tunnel Park or garden Other engineering structure Graveyard Baolis, Well Tank Cave

4. Property Use ABANDONED / IN USE: In use **Present** Living temple, the presiding deity is a patalaphuta siva linga within a circular *yonipitha* made of black chlorite. Past Worshipped. 5. Age (Source) Ganga Rule PERIOD 13th century A.D. YEARS 13th century A.D. **Precise date of Construction** Completion Subsequent changes Now the temple is completely renovated over the original base which lost the former glory of the temple. **Destruction / Demolition** 6. Ownership / Level of Protection SINGLE /MULTIPLE : Multiple **Public**: Archaeological Survey of : State Archaeology India Department / Any Other (Please specify) **Private** Any other (Please specify) Trivenisvara Yuva Parishada. Name Address At- Madhipur, Po- Konarka, Dist- Puri, Pin- 752111 Phone 7. Association WITH EVENTS In History In Rituals Sivaratri, Sitalasathi, Maghasaptami, Sankranti etc. are observed here. In Building Construction Any other (specify) Engagement, , Thread Ceremony etc. WITH PERSONS Patron Originally, the Gangas but now the Trivenisvara Yuva Parishada is looking after the temple. Architect / Engineer Any other (specify) 8. Statement of Significance Architectural Architectural : Archaeological Archaeological : Historical

century A.D

On the basis of architectural features and sculptural embellishments, the temple can be dated to the 13th

Religious

Any other (specify)

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features		
• Context Urban / Rural Setting : Surroundings	* Drawings (Attach extra sheet if necessary) : No Rural setting	
Curroundings	Stand in isolation Complex Integral part of a landscape / Street / Complex :	
• Quantification Area Dimension (L x B x H) :	17.85 mtrs x 5.00 mtrs x 8.00mtrs (approximate height) (m / cm/ feet / inch)	
Number of Blocks : Number of Storys :	Two	
• Spatial Organization Orientation : Plan :	Facing towards east Consists of a square Vimana and a recently built R.C.C flat roofed mandapa which is rectangular on plan.	
Allocation of Spaces :	30.80 mtrs(L) x30.00 mtrs(W).	
ARCHITECTURAL STYLE • Ornamentation Exteriors :	Decorated with architectural motif like <i>khakaramundi, pidhamundi, Naga-nagi</i> pilaster, divine figures like Dikpalas and other sculptural motif like <i>nayikas</i> ,	
Interiors : Movable Collections : * Any Other (specify) : 10. Construction Technology	erotics, <i>vidalas</i> , birds and animal etc. Plain Deulacharini(2 nos), Hero stone, amorous couple. The temple is <i>pancharatha</i> on plan and <i>panchanga</i> bada in elevation as evidenced from the surviving bada portion.	
10. Construction Technology		
Structural System : Building Techniques : Material of Construction :	Rekha vimana of Kalingan order. Ashlar dry masonry for the vimana Sandstone is used for the vimana and brick for the jagamohana and compound wall.	
11. Condition Assessment		
In General Good / Fair	Fair	
Sign of Deterioration Serious Deterioration Danger of Disappearance		

In Brief (Attach extra sheet if necessary):

	in a good state of pre	eservation.
		✓ Natural Negligence ✓ Vandalism Urban Pressures
x x x x x x x	< x x x x x x x x x x	x x x x x x x x x x x x x x x x x x x
	SE	CTION III: REFERENCES
13. Reference	e Sources (published	l and unpublished textual details)
1. B.K Rath 2.	, 1996, The Forgotter	n Monuments of Orissa, Vol.3, New Delhi.
14. Photogra	phs: 15 nos	
		(Attach list as in page 6, in case of multiple photographs)
Photo Refere CAPTION	nce	: :
15. Audio / Vi	deo	
		(Related to rituals / performance / festivals etc.)
Reference DESCRIPTIO	N	: :
16. Maps/Plai	ns/Drawings	
17. Listers		
NAME:	J. S. Naik	NAME:
18. Reviewers	s	
NAME: COMMENTS	Dr. S. Pradhan	NAME: COMMENTS: