

## INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

## **Documentation format for Archaeological / Heritage Sites / Monuments**

Serial No.: 0R/PRI- 19

**SECTION I: IDENTIFICATION** 1. Name Alarnatha Visnu Temple, Brahmagiri, Dist. - Puri Present Past Other Name (if any): 2. Location **LONGITUDE** 85<sup>0</sup> 39' 01" E 19<sup>0</sup> 47' 42" N LATITUDE **ELEVATION** 15 ft **Address** Village (village code) Brahmagiri Post: Brahmagiri Via: Brahmagiri Tehsil: Brahmagiri District: Puri State: Orissa PIN: 752011 Approach It is located on the left side of the road leading from Puri to Satapada in Brahmagiri town and situated 20 kms from Puri town. 3. Property Type Religious structures Other Structures Buildings Wall Palace Temple Fort Mosque Gateway Minar Pillar Citadel Govt. building Others (specify) Church Railway station Monastery Defence building Stupa Industrial building Tomb. Mausoleum Other public buildings Note: Residential building The temple has a rekha vimana. pidha iagamohana and Engineering structure Open space and related natamandapa. The present structures temple was constructed over the Bridge Public square ruined temple of the 13<sup>th</sup> century Tunnel Park or garden A.D. in which only the pista and Other engineering structure Graveyard Baolis, Well pabhaga mouldings of the Tank vimana and up to the jangha Cave portion of the jagamohana are existed.

## 4. Property Use ABANDONED / IN USE: In use **Present** Living temple, enshrining a four-armed Visnu made of black chlorite. **Past** Worshipped 5. Age (Source) PERIOD Ganga rule Originally 13<sup>th</sup> century A.D. YEARS **Precise date of Construction** Completion Subsequent changes The present temple was renovated and rebuilt by Orissa State Archaeology. **Destruction / Demolition** 6. Ownership / Level of Protection SINGLE /MULTIPLE: Multiple **Public**: Archaeological Survey of : Protected monument of Orissa State Archaeology and State Archaeology under the Endowment Department, Government of India Department / Any Other (Please Orissa. specify) **Private** Any other (Please specify) Name Orissa State Archaeology, Paryatan Bhawan, Address B.J.B. Nagar, Bhubaneswar, Orissa Phone 0674-2432147 7. Association WITH EVENTS Chaitanya visited this temple during his stay at Puri in In History the early part of the 16<sup>th</sup> century AD. In Rituals Anavasara Yatra, Sana Ekadasi, Bada Ekadasi, etc. In Building Construction Any other (specify) Marriage, thread ceremony, engagement, etc are observed here. WITH PERSONS **Patron** Originally the Gangas but now under the protection of Orissa State Archaeology. **Architect / Engineer** Any other (specify) Endowment Department, Government of Orissa. 8. Statement of Significance Architectural Architectural Archaeological : Archaeological 1 Historical Historical ✓ Religious Religious Any other (specify) On the basis of pista mouldings, remaining sculptural embellishments like- Dikpala images and the detached fragments the original temple can be dated to the 13<sup>th</sup> century A.D. over which, later on the present temple was constructed.

**SECTION II: DESCRIPTION** 

9. Physical Description and Decorative Features			
<ul> <li>Context</li> <li>Urban / Rural Setting</li> <li>Surroundings</li> </ul>	:	* Drawings (Attach extra sheet if necessary) : No Urban setting	
		Stand in Isolation Integral part of a Landscape / Street / Complex :	Complex
• Quantification Area Dimension ( L x B x H)	:	21.90 mtrs x 12.40 mtrs x 12.00 height)	mtrs (approximate
Number of Blocks Number of Storys	:	Three	(m / cm/ feet / inch)
Spatial Organization Orientation Plan  Allocation of Spaces	: :	Facing towards east The <i>vimana</i> and <i>jagamohana</i> are square on plan whereas the <i>natamandapa</i> is rectangular on plan that stands over a <i>pista</i> of 0.45 mtrs high. 42.20 mtrs (L) x 41.60 mtrs (W)	
Allocation of Spaces  ARCHITECTURAL STYLE	•	42.20 mus (L) x 41.60 mus (W)	
Ornamentation			
Exteriors Interiors	:	The temple is devoid of sculptural and architectural embellishment except the carvings of the existing bada of the jagamohana which is adorned with nayikas, dikpalas and maithuna images.  Plain, only the vimana doorjambs is carved with three	
Movable Collections * Any Other (specify)	:	sakhas. <i>Lalatabimba</i> slab, <i>Graha</i> panel and the standard that the standard in elevation.	temple members. on plan and
10. Construction Technology			
Structural System	:	Rekha vimana, pidha jagamohana of Kalingan order.	and <i>natamandapa</i>
Building Techniques Material of Construction	:	Ashlar masonry Khandolite stone	
11. Condition Assessment			
In General Good / Fair	:	Good	
Sign of Deterioration Serious Deterioration Danger of Disappearance			

In Brief (Attach extra sheet if necessary):

The temple is in a good state of preservation. 12. Threats to the Property Natural Negligence Vandalism **Urban Pressures SECTION III: REFERENCES 13. Reference Sources** (published and unpublished textual details) 1. R. P. Mohapatra, 1986, Archaeology in Orissa, Vol. - I, Delhi. 2. 14. Photographs: 36 nos (attach list as in page 6, in case of multiple photographs) **Photo Reference CAPTION** 15. Audio / Video (related to rituals / performance / festivals etc.) Reference **DESCRIPTION** 

## 17. Listers

16. Maps/Plans/Drawings

NAME D. B. Garnayak NAME:
18. Reviewers

NAME: Dr. S. Pradhan NAME:

COMMENTS COMMENTS: