

## INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS Janpath, New Delhi -110 001, www.ignca.gov.in

## **Documentation format for Archaeological / Heritage Sites / Monuments**

Serial No.: OR / PRI - 53

CECTION I . IDENTIFICATION				
1. Name	SECTION I: IDENTIFICATION			
Present  Past Other Name (if any):  2. Location	<ul> <li>Paschima Sambunath Temple, Krushnaprasad,</li> <li>Dist Puri</li> <li>Visvanatha Temple</li> <li>Kasi Visvanath</li> </ul>			
<b>LONGITUDE</b> 86° 06' 48" E	LATITUDE 20 <sup>0</sup> 04'16" N ELEVATION 42 ft			
Address	: Village (village code) Krushnaprasad Post: Krushnaprasad Via: Niali Tehsil: District: Puri State: Orissa PIN: 754004			
Approach	: The temple is situated in Krushanprasad village which is located at a distance of 5 kms south-east of Panimal chowk on the Niali-Madhava (S.H60) road and 7 kms from Amaresvara.			
3. Property Type				
Buildings  Palace Fort Citadel Government building Railway station Defence building Industrial building Other public buildings Residential building	Religious structures  ✓ Temple  Mosque  Minar  Church  Monastery  Stupa  Tomb, Mausoleum  Other Structures  Wall  Gateway  Pillar  Others (specify)			
Engineering structure  Bridge Tunnel Other engineering structure	Open space and related structures  Public square Park or garden Graveyard Baolis, Well Tank Cave  Note: The temple has a rekha vimana & pidha jagamohana of Kalingan order.			

4. Property Use	
	ABANDONED / IN USE: In use
Present	: It is a living temple that enshrines a Sivalinga within a circular <i>yonipitha</i> & one Buddhist image known as Namasangiti.
Past	: Worshipped
5. Age (Source)	
PERIOR	
PERIOD YEARS	<ul> <li>Somavamsis rule</li> <li>10<sup>th</sup> century A.D.</li> </ul>
Precise date of Construction	: 10 <sup>th</sup> century A.D.
Completion	:
Subsequent changes	: Renovated by Orissa State Archaeology under X and XI Finance Commission Award.
<b>Destruction / Demolition</b>	:
6. Ownership / Level of Protection	on
•	SINGLE /MULTIPLE : Single
Public: Archaeological Survey of India / State Archaeology Department / Any Other (Please	: Protected Monument of Orissa State Archaeology
specify) Private	•
Any other (Please specify)	·
Name	:
Address	: Orissa State Archaeology, Paryatan Bhawan, B.J.B. Nagar, Bhubaneswsar, Orissa
Phone	: 0674- 2432147
7. Association	
<ul> <li>WITH EVENTS</li> </ul>	
In History	:
In Rituals	: Sivaratri, Bada-Usha, etc.
In Building Construction Any other (specify)	: : Thread Ceremonay, engagements, etc.
WITH PERSONS	
Patron	: Originally the Somavamsis but now by the Orissa State Archaeology.
Architect / Engineer	:
Any other (specify)	:
8. Statement of Significance	
Architectural	: 🗸 Architectural
Archaeological	:
Historical Religious	: : ✓ Religious
Any other (specify)	: It is a brick temple and the architectural features assigned
	the temple to the Somavamsis period i.e. to the 10 <sup>th</sup> century A.D.

## SECTION II: DESCRIPTION

9. Physical Description and Dec	<u>ora</u> t	ive Features
Context Urban / Rural Setting Surroundings	:	* Drawings (Attach extra sheet if necessary) : No Rural Setting
		Stand in Isolation Stand in isolation Integral part of a Landscape / Street / Complex :
Quantification Area Dimension ( L x B x H)  Number of Blocks Number of Storys	: : : : :	25.60 mtrs x 4.65 mtrs x 10.00 mtrs (approximately) (m / cm/ feet / inch Two
• Spatial Organization Orientation  Plan Allocation of Spaces	:	The name of the temple itself justifies its westward facing. The <i>vimana</i> & <i>jagamohana</i> are square on plan. 27.00 mtrs (L) x 23.60 mtrs (W)
ARCHITECTURAL STYLE  • Ornamentation Exteriors  Interiors Movable Collections  * Any Other (specify)	: : : : : : : : : : : : : : : : : : : :	Decorated with architectural motifs such as <i>chaitys</i> medallion etc. Plain Architectural members like <i>amalaka sila</i> and pillars etc. On plan it is a <i>pancharatha</i> temple and <i>panchangabada</i> in elevation.
10. Construction Technology		
Structural System  Building Techniques  Material of Construction	:	The <i>vimana</i> has a curvilinear super structure whereas the <i>jagamohana</i> has a pyramidal roof of <i>Kalingan</i> order.  English bond The temple was made of bricks and sandstone was used for the platform and door frame.
11. Condition Assessment		
In General Good / Fair	:	Fair
✓ Sign of Deterioration Serious Deterioration Danger of Disappearance		

In Brief (Attach extra sheet if necessary):

It was renovated by Orissa State Archaeology in 1971-72.

12. Inreats to	tne Property	
		✓ Natural
		Negligence
		Vandalism
		Urban Pressures
XXXXXXX	<pre></pre>	X X X X X X X X X X X X X X X X X X X
	Q.F	ECTION III: REFERENCES
	<u>51</u>	CHON III. KEI EKENGES
13. Reference	Sources (published	d and unpublished textual details)
1. T. E. Don	aldson, 1986, <i>Hindu</i>	Temple Art of Orissa, Vol II, Leiden.
14. Photograp	ohs: 10 nos	
<u> </u>		(Attach list as in page 6, in case of multiple photographs)
Photo Refere	nca	
CAPTION		
o,		•
15. Audio / Vi	deo	
		(related to rituals / performance / festivals etc.)
Reference		
DESCRIPTION	N	
22001111 1101		·
16. Maps/Plar	ns/Drawings	
17. Listers		
NAME:	D.B. Garnayak	NAME:
18. Reviewers	6	
NAME :	Dr. S. Pradhan	NAME :
COMMENTS		COMMENTS ·