

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: 0R/PRI- 56

1. Name	SECTION I: IDENTIFICATION	N
Present Past Other Name (if any): 2. Location	: Kuruma; A Buddhist m : : Yama Dharma/Jama D	•
LONGITUDE 86 ⁰ 07' 24" E	LATITUDE 19 ⁰ 53' 62" N	ELEVATION 25 ft
Address	: Village (village code) Post : Bali Dokana Tehsil: Konarka State : Orissa	Kuruma Via: Konarka District: Puri PIN: 752111
Approach	Konarka–Kakatapur ro Konarka. It can be ap	s situated on the left side of the oad and is about 6 km from oproached by a road branching nowk and is about 2 km from the
3. Property Type		
Palace Fort Citadel Govt. building Railway station Defense building	Religious structures Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum	Other Structures Wall Gateway Pillar Others (specify):
Industrial building Other public buildings Residential building		Note: This is a Buddhist monastery having twelve cells and an open
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structures Public square Park or garden Graveyard Baolis, Well Tank Cave	courtyard at the centre. The site was first reported by Brajabandhu Das, a local school teacher and subsequently excavated by Orissa state Archaeology from 1971 to 1975 A.D. On the basis of unearthed material the site can be dated to the 10 th century A.D.

4. Property Use ABANDONED / IN USE: In use Present The monastery is abandoned now but the images retrieved from the site now worshiped within a small shed. Past Worshipped. 5. Age (Source) Somavamsi Rule PERIOD **YEARS** 9th - 10th centuries A.D. 9th - 10th centuries A.D. **Precise date of Construction** Completion Subsequent changes Excavated and conserved by the Orissa State Archaeology. **Destruction / Demolition** 6. Ownership / Level of Protection SINGLE /MULTIPLE : Multiple **Public**: Archaeological Survey of : Protected site of Orissa State Archaeology / State Archaeology Department / Any Other (Please specify) Private Any other (Please specify) Orissa State Archaeology Name Address Paryatan Bhavan, BJB Nagar, Bhubanesvara Phone 0674-2432147 7. Association WITH EVENTS In History In Rituals Buddha purnima mahostava(may 21 & 22) In Building Construction Any other (specify) Engagement, , Thread Ceremony etc. • WITH PERSONS Originally the Somavamsi, but now the Orissa State Patron Archaeology Architect / Engineer Any other (specify) 8. Statement of Significance Architectural Architectural Archaeological : Archaeological

the 10th century A.D.

On the basis of the antiquities and sculptures unearthed from the excavation the site can be dated to

Historical Religious

Any other (specify)

SECTION II: DESCRIPTION

9. Physical Description and Deco	orati	ve Features	
 Context Urban / Rural Setting Surroundings 	:	* Drawings (Attach extra sheet if	necessary) : No Rural setting
		Stand in isolation Integral part of a landscape / Street / Complex :	complex
 Quantification Area Dimension (L x B x H) 	:	29.00 mtrs x 29.00 mtrs x 2.10mtr	rs
•			(m / cm/ feet / inch)
Number of Blocks Number of Storys	:	Twelve 	
Spatial Organization			
Orientation	:	Oriented east to west.	
Plan	:	The monastery in whole square are rectangular on plan.	•
Allocation of Spaces	:	29mtrs x29mtrs in length and brea	adth respectively.
ARCHITECTURAL STYLE • Ornamentation Exteriors Interiors Movable Collections * Any Other (specify)	:	plain Plain Buddha in <i>Bhumisparsa mudra</i> , <i>F</i> an image of Tivikrama. The concept pf pillared verand Instead of pillar, the wall of the co	dah is absent here. ourt yard used as load
10. Construction Technology		verandah.	
Structural System Building Techniques Material of Construction	:	The monastic complex consists of each cardinal direction and a centre. In between cells and congiven. English bond Bricks (0.36x0.24x0.08mtrs) ar constructional purpose except to which is made of khandolite stones.	large courtyard the central courtyard a passage is re mostly used for the central courtyard
11. Condition Assessment			
In General Good / Fair	:	Fair	
Sign of Deterioration Serious Deterioration Danger of Disappearance In Brief (Attach extra sheet if neo	ess	ary):	

12. Threats to	the Property	
x x x x x x x	xxxxxxxx	Natural Negligence Vandalism Urban Pressures
	<u>s</u>	ECTION III: REFERENCES
13. Reference	Sources (publishe	d and unpublished textual details)
1. R.P Moha	patra, 1986, Archa	eology in Orissa, vol. 1,New Delhi.
14. Photograp	hs: 09 nos	
		(Attach list as in page 6, in case of multiple photographs
Photo Referei	nce	: :
15. Audio / Vi	deo	
		(Related to rituals / performance / festivals etc.
Reference DESCRIPTION	١	: :
16. Maps/Plan	s/Drawings	
17. Listers		
NAME:	A.R. Sahoo	NAME:
18. Reviewers	3	
NAME:	Dr. S. Pradhan	NAME:

COMMENTS:

COMMENTS

The conservation work done by Orissa State Archaeology was not properly executed as modern bricks were used in large number in a half hazard manner.