

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR / PRI - 62 **SECTION I: IDENTIFICATION** 1. Name Present Pandita Matha, Narasimha Patna, Dist. - Puri Past Other Name (if any): 2. Location **LONGITUDE** 85° 42′ 10″ E 19⁰ 45' 50" N LATITUDE **ELEVATION** 70 ft Address Village (village code) Narasimha Patna Post: Palanka Via: Brahmagiri Tehsil: Brahmagiri District: Puri State: Orissa PIN: 752011 **Approach** The monastry is located on the left bank of the river Bhargavi and at a distance of one km from the shore. It can be approached on the left side of NH.-203 leading from Puri to Satapada branching at a distance of 6.5 kms from Kathuari chowk of Brahmagiri township via Harchandi temple. 3. Property Type **Buildings** Religious structures Other Structures Palace Temple Wall Fort Mosque Gateway Citadel Minar Pillar Govt. building Church Others (specify) Railway station Monastery Defence building Stupa Industrial building Tomb, Mausoleum Note: Other public buildings Residential building The monastry is of Marath period and the local considered Engineering structure Open space and related it as a sacred place. structures Bridge Public square Tunnel Park or garden Other engineering structure Graveyard Baolis. Well Tank

	Cave		
4. Property Use			
	ABANDONED / IN USE: Abandoned		
Present	: Abandoned and dilapidated condition. However, one of the room of the <i>matha</i> , enshrines the deities - lord Jagannatha, Balabhadra and Subhadra which is under worshipped.		
Past	: Residential complex		
5. Age (Source)			
PERIOD YEARS Precise date of Construction Completion Subsequent changes Destruction / Demolition	 Maratha rule 18th century A.D. Second half of the 18th century AD. 		
6. Ownership / Level of Protection			
Public: Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)	 SINGLE /MULTIPLE: No claimant of the <i>Mathas</i> but the deities are looked after by the villagers. 		
Private Any other (Please specify) Name Address Phone 7. Association	: : :		
WITH EVENTS In History In Rituals In Building Construction Any other (specify) WITH PERSONS Patron Architect / Engineer Any other (specify) 8. Statement of Significance	: : Rajayatra, Netraustava, etc are observed here. : : : Villager of Narasimhapatna : :		
Architectural Archaeological Historical Religious Any other (specify)	 ∴ Architectural ∴ Archaeological ∴ On architectural ground and local tradition the monastery can be assigned to the Maratha rule in Orissa i.e. the second half of the 18th century AD. 		

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

* Drawings (Attach extra sheet if necessary): Context No Rural setting

Urban / Rural Setting

Surroundings

Stand in Isolation

Integral part of a Landscape /

Street / Complex:

Street

Quantification

Area Dimension (LxBxH) 30.00 mtrs x 35.00 mtrs x 9.00 mtrs (existing height)

(m / cm/ feet / inch)

Number of Blocks 52 rooms Number of Storys Double storied

Spatial Organization

Orientation Oriented south-west to north-east and the entrance is

facing towards south east.

Plan The monastery is rectangular on plan having a central

courtyard measuring 14.20 mtrs x 10.50 mtrs in length and width respectively surround by residential rooms.

Allocation of Spaces 30.00 mtrs (L) x 35.00 mtrs (W)

ARCHITECTURAL STYLE

Ornamentation

Exteriors

Interiors The central courtyard surrounded by residential rooms

having vaulted ceiling with arch entrance.

Movable Collections Nil

* Any Other (specify) Two inscriptions are found one on each side of the

> main entrance. The inscription on the right side has 9 lines out of which 3 lines are in Urdu script and the rest are in Oriya script written within a space of 0.75 mtrs x 0.47 mtrs in length & width respectively. The inscription on the left side bearing six lines within a space of 0.85 mtrs x 0.30 mtrs written in one of the

south Indian script.

10. Construction Technology

Structural System Structural monastery **Building Techniques** English bond technique

Material of Construction Bricks and lime mortar are used for the structure

whereas the entire surface is thickly lime plastered.

11. Condition Assessment

In General Good / Fair

✓ Serious [eterioration Deterioration f Disappearance	
In Brief (Attach extra sheet if necessary):		
The monastry is in worst condition and facing both biological and structural problems such as growth of vegetation, bird excreta, water seepage and cracks developed on the roof and walls .		
12. Threats to	the Property	
x x x x x x x	\rightarrow \right	Natural Negligence Vandalism Jrban Pressures X X X X X X X X X X X X X X X X X X X
SECTION III: REFERENCES		
13. Reference Sources (published and unpublished textual details)		
1 2.		
14. Photograp		
	•	attach list as in page 6, in case of multiple photographs)
Photo Refere	nce :	
15. Audio / Vi	deo	
		(related to rituals / performance / festivals etc.)
Reference DESCRIPTION	i N :	
16. Maps/Plar	ns/Drawings	
17. Listers		
NAME	Jaya Shankar Naik	NAME:
18. Reviewers	5	
NAME: COMMENTS	Dr. S. Pradhan	NAME: COMMENTS: