

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR / PRI - 16 **SECTION I: IDENTIFICATION** 1. Name Present Chakra Narasimha Temple, Puri town, Dist. – Puri Past Santi Narasimha Other Name (if any): : Sasur Badi 2. Location **LONGITUDE** 85⁰50'67"E 19⁰48'03"N LATITUDE **ELEVATION** 24 Ft. **Address** Village (village code) Chakratirtha Road, Puri Post: Puri Via: Puri Tehsil: Puri **District:** Puri State: Orissa PIN: Approach It is located on the right side of Chakratirtha Road, leading from Netajee Subas Bose Chowk to Penthakote, Puri. It is about 60.00 mtrs south of Sunara Gauranga Ashrama and 30 mtrs north of sea shore. 3. Property Type Buildings Religious structures Other Structures Palace Temple Wall Fort Mosque Gateway Citadel Minar Pillar Govt. building Church Others (specify) Railway station Monastery Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Engineering structure Open space and related Note: structures The temple is consisting of a Bridge Public square pidha vimana and a frontal Tunnel Park or garden porch of Kalingan order. Other engineering structure Graveyard Baolis, Well Tank Cave

4. Property Use		
		ABANDONED / IN USE: In use
Present	:	In trhis living temple, the presiding deities are three images of Narasimha of different size.
Past	:	Worshipped.
5. Age (Source)		
PERIOD YEARS Precise date of Construction Completion Subsequent changes Destruction / Demolition	: : : : : : : : : : : : : : : : : : : :	Ganga period 14 th century AD
6. Ownership / Level of Protection	on	
		SINGLE /MULTIPLE : Multiple
Public: Archaeological Survey of India / State Archaeology Department / Any Other (Please specify) Private Any other (Please specify) Name Address Phone	: : : : : : : : : : : : : : : : : : : :	Jagannath Temple Administration Jagannath Temple Administration Grand Road, Puri
7. Association		
WITH EVENTS In History In Rituals In Building Construction Any other (specify) WITH PERSONS Patron Architect / Engineer Any other (specify) 8. Statement of Significance	: : : : : : : : : : : : : : : : : : : :	Narasimha Janma, Agnyamala of Lord Jagannath comes to the deity once a year Jagannath temple Administration
Architectural Archaeological Historical Religious Any other (specify)	✓ : : ✓	Architectural On the basis of architectural features, the temple can be

On the basis of architectural features, the temple can be assigned to the 14^{th} century AD i.e. Ganga period.

SECTION II: DESCRIPTION

9. Physical Description and Dec	cora	
 Context Urban / Rural Setting Surroundings 	:	* Drawings (Attach extra sheet if necessary) : No Urban Setting
•		Stand in Isolation Street Integral part of a Landscape / Street / Complex :
 Quantification 		
Area Dimension (L x B x H)	:	6.30 mtrs x 6.30 mtrs x 9.25 mtrs. (L x B x D) (m / cm/ feet / inc
Number of Blocks Number of Storys	:	Two NA
Spatial Organization		
Orientation	:	The temple is facing towards north
Plan	:	The temple is square on plan.
Allocation of Spaces	:	8.00 mtrs x 8.00 mtrs (L x B)
ARCHITECTURAL STYLE		
Ornamentation		The common deviates which as the common formation of the common deviates and t
Exteriors		The parsvadevatas niches houses image of rece installation. The dvarapala niches houses four arms vaisnavite dvarapalas standing over a plain pedestal wi outstretched legs. Their major right arms in abhay mudra while their left arm is resting over a mace. The upliftment back hands hold disc in the left and conch the right. The architecture above the doorjamb measuring 2.10 mtrs are carved with Navagrahas seate in padmasana within semicircular niches flanked by twatlant ganas.
Interiors	:	Plain
Movable Collections * Any Other (specify)	:	Nil The temple is <i>panchangabada</i> in elevation.
10. Construction Technology		
Structural System Building Techniques Material of Construction	:	Pidha vimana of Kalingan order. Dry Masonry Laterite and Sandstone.
11. Condition Assessment		
In General Good / Fair	:	Fair
✓ Sign of Deterioration✓ Serious DeteriorationDanger of Disappearance		

In Brief (Attach extra sheet if necessary):								
The temple is progressively encroa north.	ch	ed by private residential	buildings	in west,	south	and		
12. Threats to the Property								
,	✓	Natural						
,	✓	Negligence						
•	✓	Vandalism						
,	√	Urban Pressures						

		Urban Pressures		
x x x x x x x x	x x x x x x x x x x x	x x x x x x x x x x x x x x x x x x x		
SECTION III: REFERENCES				
13. Reference Sources (published and unpublished textual details)				
1.				
14. Photographs	3			
		(attach list as in page 6, in case of multiple photographs)		
Photo Reference CAPTION	9 : :			
15. Audio / Video	0			
		(related to rituals / performance / festivals etc.)		
Reference DESCRIPTION	:			
16. Maps/Plans/Drawings				
47 Lintoro				
17. Listers				
NAME: B	B. B. Satpatty	NAME:		
18. Reviewers				

NAME:

COMMENTS:

NAME: Dr. S. Pradhan

COMMENTS