

4. Property Use

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR / PRI - 32 **SECTION I: IDENTIFICATION** 1. Name Present Jhadesvari Temple, Station Bazaar Road, Puri Town, Dist.- Puri Past Other Name (if any): 2. Location **LONGITUDE** 85° 50' 04" E LATITUDE 19⁰ 48['] 48^{''} N **ELEVATION** 10 ft **Address** Village (village code) Station Bazaar Road Post: Bali Sahi Via: Puri town Tehsil: Puri town **District:** Puri State: Orissa **PIN**: 752001 Approach The temple is located in the precinct of Panjabi Matha in the central courtyard. It can be approached on the left side of the road leading from Emar Matha to Ganduachura chowk and situated at distance of 10 mtrs south of the outer compound wall of Jagannath temple. 3. Property Type Buildings Religious structures Other Structures Wall Palace Temple Mosque Fort Gateway Citadel Minar Pillar Govt. building Church Others (specify) Railway station Monastery Defense building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Engineering structure Open space and related Note: structures The temple has a pidha Bridge Public square vimana of Kalingan order. Park or garden Tunnel Other engineering structure Gravevard Baolis, Well Tank Cave

Present Past	:	ABANDONED / IN USE: In use Living temple, the presiding deities are Jagannath, Bhalabhadra, Subhadra, Raghunath, Rama-Laxmana, Sita and Radha- Krisna. Worshipped.				
5. Age (Source)						
PERIOD YEARS Precise date of Construction Completion Subsequent changes Destruction / Demolition	: : : : : : : : : : : : : : : : : : : :	Bhoi Gajapati rule. 17 th century A.D				
6. Ownership / Level of Protection	on					
		SINGLE /MULTIPLE : Multiple				
Public: Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)	:	Endowment Department, Government of Orissa.				
Private Any other (Please specify)	:	Under the care and maintenance of the <i>Matha Mahanta</i> Sri Balaram Das Goswami.				
Name Address Phone	:	 				
7. Association						
 WITH EVENTS In History In Rituals In Building Construction Any other (specify) WITH PERSONS 	: : : : : : : : : : : : : : : : : : : :	Releted with the history of Panjabi <i>Matha</i> . <i>Ramanavami, Janmastami, Snanapurnima, Sankranti</i> etc. are observed here				
Patron Architect / Engineer	:	Endowment Department, Government of Orissa.				
Any other (specify)	:	Matha Mahanta Sri Balaram Das Goswami.				
8. Statement of Significance						
Architectural Archaeological Historical Religious	1	Architectural Archaeological				
Any other (specify)	:	On the basis of architectural features, the temple can be assigned to the 17 th century AD. i.e. the Bhoi Gajapati rule of the Khurda Kingdom.				

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features									
• Context Urban / Rural Setting : Surroundings	* Drawings (Attach extra sheet if necessary):No Urban setting								
3	Stand in isolation/ Complex Integral part of a landscape / Street / Complex :								
• Quantification Area Dimension (L x B x H) :	7.50 mtrs x 7.50 mtrs x 5.90 mtrs (m / cm/ feet / inch)								
Number of Blocks : Number of Storys :	One N.A								
• Spatial Organization Orientation : Plan : Allocation of Spaces :	Facing towards east. The <i>vimana</i> is square on plan. 7.50 mtrs x 7.50 mtrs (L X W)								
ARCHITECTURAL STYLE Ornamentation Exteriors :	Devoid of any decoration except two dopichhasimare noticed in the corner and three divinities at the centre in the kanthi of each recess. The ghanta decorated with lotus design.								
Interiors : Movable Collections : * Any Other (specify) :	Plain. Nil The temple is <i>pancharatha</i> on plan and <i>panchangabada</i> in elevation.								
10. Construction Technology									
Structural System : Building Techniques : Material of Construction : 11. Condition Assessment	Pidha vimana of impoverished Kalingan order. Ashlar masonry with lime mortar. Laterite and bricks and entire surface is plastered and white washed.								
In General Good / Fair Good									
	Sign of Deterioration Serious Deterioration Danger of Disappearance								

In Brief (Attach extra sheet if necessary):

The temple is in a good state of preservation.

12. Threats to the Property

		✓ 	Natural Negligence Vandalism Urban Pres	sures					
X x	x x	x	x x	x	x	x	x	х	x
		<u>SECTI</u>	ON III: REF	ERENC	ES				
13. Referen	ce Sources (p	ublished and	unpublished	l textual o	details	s)			
14. Photogr	aphs								
			(Attach list a	s in page	6, in	case of	multiple	e photo	graphs)
Photo Refero	ence	:							
15. Audio / '	Video		(D. I			, ,		, <u>, , , , , , , , , , , , , , , , , , </u>	
			(Rela	ated to rit	uals,	/ perfor	mance,	/ festiva	als etc.
Reference DESCRIPTION	ON	:							
16. Maps/PI	ans/Drawings	; 							
17. Listers									
NAME :	J.S Naik		NAME	:					
18.Reviewe	rs								
NAME : COMMENTS	Dr. S. Prad	han	NAME :						