

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR / PRI - 33

SECTION I: IDENTIFICATION

1. Name

Present : Kaliya Dalana Temple, Puri town, Dist-Puri

Past

Other Name (if any): :

2. Location

LONGITUDE 85⁰48'94"E LATITUDE 19⁰48'62"N ELEVATION 16 ft

Address : Village (village code) Markandesvara Sahi, Puri Town

Post : Puri Via: Puri Town Tehsil: Puri District: Puri

State : Orissa PIN:

Approach: The temple is located within the precinct of Markandesvara

Siva Temple, Markandesvara Sahi, Puri. One can approached to the site on the right side leading from upara

Wall

Pillar

Note:

noticed.

Gateway

Others (specify)

The temple is of Gaudiya style, a

Markanda Sahi to Puri-Brahmagari road.

3. Property Type

Buildings Religious structures Other Structures

Palace ✓ Temple
Fort Mosque
Citadel Minar
Govt. building Church
Railway station Monastery

Defence building
Industrial building
Tomb, Mausoleum

Industrial building Other public buildings Residential building

Engineering structure Open space and related

Structures
Bridge Public square

Tunnel Park or garden type of temple architecture that prevails in Bengal. In Orissa only Other engineering structure Graveyard few temple of this style are

Baolis, Well Tank Cave 4. Property Use ABANDONED / IN USE: Abandoned Present Non living, the enshrined deity is Benu Gopala in tribhanga pose. Worshipped Past 5. Age (Source) PERIOD Maratha Period YEARS 18th Century AD. **Precise date of Construction** 1745 AD Completion Subsequent changes **Destruction / Demolition** 6. Ownership / Level of Protection **SINGLE /MULTIPLE:** Multiple **Public**: Archaeological Survey: Endowment Department, Government of Orissa of India / State Archaeology Department / Any Other (Please specify) **Private** Priest of the temple Any other (Please specify) Narsinmha Tiadi, Chief Priest Name Address Upara Markandesvara Sahi, Puri Phone 7. Association WITH EVENTS In History : Constructed by Vardhaman, a king of Bengal in Saka era 1667. Janmastami, Sivaratri, Risi Panchami etc are In Rituals observed. In Building Construction Any other (specify) ---WITH PERSONS Endowment Department, Government of Orissa. Patron Architect / Engineer Any other (specify) 8. Statement of Significance Architectural Architectural Archaeological Historical

Religious

Religious

Any other (specify)

On the basis of the written records, the precise date of the

construction of temple is 1745 AD, i.e. Saka era 1667 and

built by King Vardhamana of Bengal.

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

Context

* **Drawings** (Attach extra sheet if necessary) No

Urban setting

Urban / Rural Setting

Surroundings

Stand in Isolation

Street

Integral part of a Landscape /

Street / Complex:

Quantification

Area Dimension (LxBxH) 4.50 mts x 6.40 mts x 6.00 mts

(m / cm/ feet / inch)

Number of Blocks Single Number of Storys N.A

Spatial Organization

Orientation Facing towards south

Plan The temple is rectangular on Plan 4.90 mtrs (L) x 6.80 mtrs (B) Allocation of Spaces

ARCHITECTURAL STYLE

Ornamentation

Exteriors Plain

Interiors The presiding deity is made of black chlorite. The

deity is of unknown origins. Stands on a decorated pedestal. At the base of the pedestal the male worshipper in aradhana pose are noticed on either side. Above it in the back side there are two female attendants crowned with Kirita Mukuta. The whole image is decorated with different scenes relating to lord Krishna. The image measure 1.20 mtrs in

height x 0.80 mtrs in width.

Movable Collections Nil

* Any Other (specify) The temple is unique in its architecture and famous

in Bengal which gave the name to this temple style

as Gaudiya Style.

10. Construction Technology

Structural System Gaudiya type of temple

Building Techniques Dry masonry

Material of Construction Sandstone and vellow lime wash

1	1.	Con	dition	Asse	ssment
---	----	-----	--------	------	--------

In General	Good / Fair :	Fair		
	✓ Sign of Deterioration Serious Deterioration			
	Danger of Disappearance			
	ra sheet if necessary)	wth of vegetation is noticed over		
12. Threats to the	Property			
	✓ Natural ✓ Negligence ✓ Vandalism			
x x	x x x x x x x	sures x x x x x		
	SECTION III: RE	EFERENCES		
1.	u 1	,		
14. Photographs	(attach list as in n	(attach list as in page 6, in case of multiple photogra		
	(attach list as in p	rage 6, in case of multiple photogra		
Photo Reference CAPTION	: :			
15. Audio / Video				
	(related	l to rituals / performance / festivals		
Reference DESCRIPTION	: :			
16. Maps/Plans/Dra	awings			
17. Listers				
NAME: B. B.	Satpathy NAME :			
18. Reviewers				
NAME: Dr. S	S. Pradhan NAME :			