

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

		<u>Serial No.: 0R / PRI -</u> 48
1. Name	SECTION I: IDENTIFICATION	
Present Past Other Name (if any): 2. Location	: Nanak Matha, Swargad ¹ :	vara, Puri Town, Dist Puri
Z. Location		
LONGITUDE 85° 49' 10" E	LATITUDE 19 ⁰ 47 ['] 67 ["] N	ELEVATION 30 ft
Address	: Village (village code) Post : Bali Sahi Tehsil: Puri town State : Orissa	Swargadvara , Puri Via: Puri town District: Puri PIN: 752001
Approach		near Swargadvara, Puri and of Bali Sahi Road leading from Ivara.
3. Property Type		
Buildings Palace Fort Citadel Govt. building Railway station Defense building Industrial building Other public building Residential building	Religious structures Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum	Other Structures Wall Gateway Pillar Others (specify)
Engineering structure Bridge Tunnel Other engineering structure	structures Public square Park or garden Graveyard Baolis, Well Tank Cave	Note: The double storied Nanak Matha is a monastic establishment of Nanak's Udasina sect. Its branches are found both in Puri and other district. In Puri its branch monasteries are Mangu and Advita Das Matha located in front of Simhadvara and sea beach respectively, in cuttack district its branches are in Pahala (Bhubaneswar-Cuttack Road) and Kaliaboda in Tulasipur.

4. Property Use		
Present	:	ABANDONED / IN USE: In use Living Matha, the enshrining deities are Radha, Krishna, Jagannath, Laxmi and Gopala. It belongs to Nanak's Udasina sect.
Past	:	It was used for the temporary residents of the pilgrims.
5. Age (Source)		
PERIOD YEARS Precise date of Construction Completion Subsequent changes Destruction / Demolition	: : : : : : : : : : : : : : : : : : : :	Bhoi rule of Khurda State. 18 th century A.D
6. Ownership / Level of Protection	n	SINGLE /MULTIPLE : Single
Public: Archaeological Survey of India / State Archaeology Department / Any Other (Please specify) Private Any other (Please specify) Name Address Phone	: : : : : : : : : : : : : : : : : : : :	Under the care and maintenance of <i>Matha Mahanta</i> Sri Satyanarayana Das
7. Association		
WITH EVENTS In History In Rituals In Building Construction Any other (specify) WITH PERSONS Patron Architect / Engineer Any other (specify) 8. Statement of Significance	: : : : : : : : : : : : : : : : : : : :	Pana Sankranti, Debasnana purnima, Janma stami etc are observed here. Marriage and thread ceremony are observed. Matha Mahanta Sri Satyanarayana Das.
Architectural Archaeological Historical Religious Any other (specify)	:	Architectural Archaeological On the basis of building materials, the <i>Matha</i> can be assigned to the 18 th century AD i.e. the Bhoi rule of Khurda

State.

SECTION II: DESCRIPTION

9. Physical Description and D	ecorat	ive Features				
Context Urban / Rural Setting Surroundings	:	* Drawings (Attach extra sheet if	necessary):No Urban setting			
Cancanango		Stand in isolation/ Integral part of a landscape / Street / Complex :	complex			
• Quantification Area Dimension (L x B x H)	:	40 mtrs x 40 mtrs x 12 mtrs	(m / cm/ feet / inch)			
Number of Blocks Number of Storys	:	25 rooms Two	(III / GIT# TEGET IIIGH)			
 Spatial Organization Orientation Plan Allocation of Spaces 	: : :	Facing towards west. Square on plan. 40 mtrs(L)x 40 mtrs(W)				
• Ornamentation Exteriors	:					
Interiors Movable Collections	:	The Matha has central courtyards measuring 10 square mtrs provided with rooms in the eastern, western and northern sides along with pillared verandah. Out of 25 rooms, four rooms on the eastern side are used for monastic activities and rituals and the rest are on rent. Nil				
* Any Other (specify)	:	There is a step well known as <i>Kua</i> measures 2.05 mtrs in diame on the south of the central court of steps and the water is used for drinking purposes.	eter and 10 mtrs deep tyard. It has 39 flights			
10. Construction Technology	•					
Structural System Building Techniques Material of Construction	: : :	Double storied <i>Monastery</i> Ashlar masonry. Brick, lime and cement.				
11. Condition Assessment						
In General	Good	/ Fair Good				
	√	Sign of Deterioration Serious Deterioration Danger of Disappearance				
In Brief (Attach extra sheet if	necess					

It is in a good state of preservation.

12. Threats	to the Property							
		N V	atural egligence andalism rban Press	sures				
X x	x x	x x	x	x	х	x	х	X
		SECTION	<u>III:</u> REF	EREN	CES			
13. Referen	ce Sources (publis	shed and u	npublished	I textual	l details	5)		
14. Photogr	aphs							
		(At	tach list as	s in pag	e 6, in o	case of	multiple	photographs
Photo Reference CAPTION	ence	:						
15. Audio / \	Video							
			(Rela	ated to i	rituals, <i>i</i>	perfori	mance,	/ festivals etc
Reference DESCRIPTION	ON	: :						
16. Maps/PI	ans/Drawings							
17. Listers								
NAME :	J.S Naik		NAME	:				
18.Reviewe	rs							
NAME : COMMENTS	Dr. S. Pradhan		NAME : COMME					