

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: 0R / PRI - 52 SECTION I: IDENTIFICATION 1. Name Narasimha Temple, Harachandi Sahi, Puri Town, Present Dist.- Puri Past Other Name (if any): 2. Location **LONGITUDE** 85° 48' 86" E LATITUDE 19⁰ 48['] 22["] N **ELEVATION** 22 ft Address Village (village code) Lokanath road, Harachandi Sahi Post: Harachandi Sahi Via: Puri town Tehsil: Puri District: Puri State: Orissa **PIN**: 752001 Approach The temple is located within the precinct of Kusani Khuntia Jaga-Ghara. It is situated on the left side of Lokanath road leading from Gandua chaura chowk to Lokanath temple, Harachandi Sahi, Puri. 3. Property Type **Buildings** Religious structures **Other Structures** Palace Temple Wall Fort Mosque Gateway Citadel Minar Pillar Govt. building Church Others (specify) Railway station Monastery Defense building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Engineering structure Open space and related structures The temple has pidha vimana of Bridge Public square impoverished Kalingan order. Tunnel Park or garden Other engineering structure Graveyard Baolis, Well Tank Cave

4. Property Use									
Present Past	:	ABANDONED / IN USE: In use Living temple, the enshrined deity is a four armed Narasimha standing over a decorated pedestal. Worshipped.							
5. Age (Source)									
PERIOD YEARS Precise date of Construction Completion Subsequent changes Destruction / Demolition	: : : : : : : : : : : : : : : : : : : :	Suryavamsi Gajapati rule. 15 th century A.D							
6. Ownership / Level of Protection									
		SINGLE /MULTIPLE : Multiple							
Public: Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)	:								
Private	:	Kusuni Khuntia Jaga Ghara Committee.							
Any other (Please specify)	:								
Name Address	:	At- Lokanath road, Po- Harachandi Sahi, Puri Town,							
	•	Dist-Puri, Orissa.							
Phone	:								
7. Association									
• WITH EVENTS									
In History	:								
In Rituals	:	Janmastami, Ramanavami, Nrusingha janma etc are observed here.							
In Building Construction	:	 Dur 6 1 1 1 1 1							
Any other (specify) • WITH PERSONS	:	Public meetings are also held here.							
Patron									
Architect / Engineer	:								
Any other (specify)	:	Kusuni Khuntia Jaga Ghara Committee.							
8. Statement of Significance									
Architectural Archaeological Historical Religious	1	Architectural Archaeological							
Any other (specify)	:	On the basis of architectural features and iconographical features of the presiding deity, the temple can be assigned to the 15 th century A.D. i.e. the Suryavamsi Gajapati rule.							

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features								
Context Urban / Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary):No Urban setting						
Carroundingo		Stand in isolation/ Integral part of a landscape / Street / Complex :	Street					
 Quantification 								
Area Dimension (LxBxH)	:	2.65 mtrs X 2.65 mtrs X 7.55 mtrs.	(m / cm/ feet / inch)					
Number of Blocks Number of Storys	:	One N.A.	(III / GIII/ ICCL / IIIGII)					
Spatial Organization								
Orientation	:	: The <i>Matha</i> is facing towards north.						
Plan Allocation of Spaces	:	The <i>Vimana</i> is square on plan. 2.60 mtrs (L) X 2.65 mtrs(W)						
• Ornamentation Exteriors Interiors Movable Collections * Any Other (specify)	:	Decorated with <i>dopichha-simha</i> and Ganesa images over the <i>Beki, Nagi</i> column carved on either sides of the doorjambs and two Narasimha images inserted within the niches at the center of the door jambs. Plain. Nil The temple has <i>panchangabada</i> in elevation and a <i>navagraha</i> panel in the architrave of the entrance.						
10. Construction Technology								
Structural System Building Techniques Material of Construction 11. Condition Assessment	:	Pidha Vimana of impoverished Kalingan order. Ashlar masonry. Sandstone and the entire surface are plastered and white washed.						
In General	G	ood / Fair : Fair						
	√	Sign of Deterioration Serious Deterioration Danger of Disappearance						

In Brief (Attach extra sheet if necessary):

The temple is in a good state of preservation. **12. Threats to the Property**

			Natural Negligence Vandalism Urban Pres						
X x	x x	X	x x	х	х	Х	х	х	х
		SECTIO	<u>ON III:</u> RE	FEREN	CES				
13. Referenc	e Sources (publi	shed and	unpublishe	ed textual	l details	s)			
14. Photogra	phs								
		(,	Attach list a	as in pag	e 6, in	case of	multiple	e photo	graphs)
Photo Reference CAPTION	nce	:							
15. Audio / V	ideo		/D =	lata d ta .	-:4 ! -	/ f		/ f = s + :	-l4- \
-			(Re	lated to i	illuais,	penor	mance,	/ iestiva	ais etc.)
Reference DESCRIPTIO	N	:							
16. Maps/Pla	ns/Drawings								
17. Listers									
NAME :	J.S Naik		NAMI	Ε:					
18.Reviewers	S								
NAME : COMMENTS	Dr. S. Pradhan		NAME COMM	: MENTS :					