

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

	Serial No.: OR / PRI - 68			
1. Name	SECTION I: IDENTIFICATION			
Present Past Other Name (if any): 2. Location	: Ramachandi Temple, P : :	uri Town, Dist Puri		
LONGITUDE 85 ⁰ 50 ¹ 18" E	LATITUDE 19 ⁰ 48 ['] 66 ^{''} N	ELEVATION 26 ft		
Address	: Village (village code)	Bankimuhana Ramachandi Sahi.		
	Post:Ramachandi Sahi Tehsil: Puri town State: Orissa	Via: Puri town District: Puri PIN: 752001		
Approach	Ramachandi Sahi, P	ated in the Bankimuhana uri. It is situated on the left ing from Red Cross Road to		
3. Property Type				
Buildings Palace Fort Citadel Govt. building Railway station Defense building Industrial building Other public buildings Residential building	Religious structures Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum	Other Structures Wall Gateway Pillar Others (specify)		
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structures Public square Park or garden Graveyard Baolis, Well Tank Cave	Note: The temple has a <i>rekha vimana</i> and a <i>pidha jagamohana</i> of <i>Kalingan</i> order.		

4. Property Use		
		ABANDONED / IN USE: In use
Present	:	Living temple, the enshrined deity is a six armed
Dood		Mahisasuramardini Durga killing buffalo demon.
Past	٠	Worshipped.
5. Age (Source)		
PERIOD	:	Bhoi rule.
YEARS	:	17 th century A.D.
Precise date of Construction	:	
Completion	:	
Subsequent changes	:	
Destruction / Demolition	:	
6. Ownership / Level of Protection	n	
		SINGLE /MULTIPLE : Multiple
Public: Archaeological Survey of	:	
India / State Archaeology		
Department / Any Other (Please		
specify)		
Private	:	
Any other (Please specify)	:	Under the care and maintenance of the chief priest
Name		Bansidhara Pani. Bansidhara Pani
Address	:	Ramachandi Sahi, Puri.
Phone	:	
7. Association		
WITH EVENTS In History		
In Rituals	:	Dasahara, Kalipuja etc. are observed here.
In Building Construction	:	
Any other (specify)	:	According to local tradition, the deity is named Ramachandi
		because lord Rama worshipped the present deity Chandi for
WITH DEDOONS		her blessing to attain victory over Ravana.
WITH PERSONS Patron	:	Originally the Bhois, but now it is under the care of
ration	•	chief priest of the temple Bansidhara Pani.
Architect / Engineer	:	
Any other (specify)	:	
8. Statement of Significance		
Architectural	1	Architectural
Archaeological Historical	•	Archaeological
Religious		
Any other (specify)	:	On the basis of architectural features and sculpture of the
		temple, it can be assigned to the Bhoi of Khurdha, i.e. 17 th
6.	· C -	century AD.
<u>3E</u>	U	<u> </u>

9. Physical Description and Dec	orative Features
• Context Urban / Rural Setting : Surroundings	* Drawings (Attach extra sheet if necessary):No Urban setting
	Stand in isolation/ Street Integral part of a landscape / Street / Complex :
• Quantification Area Dimension (L x B x H) :	3.50 mtrs x 3.50 mtrs x 9.17 mtrs(<i>Vimana</i>), 4.50mtrs x 4.50 mtrs x 5.90 mtrs(Jagamohana) (m / cm/ feet / inch)
Number of Blocks : Number of Storys :	Two N.A
• Spatial Organization Orientation : Plan : Allocation of Spaces :	Facing towards south. The <i>vimana</i> and the <i>jagamohana</i> are square on plan. 8mtrs x 9 mtrs (L x W)
ARCHITECTURAL STYLE • Ornamentation Exteriors :	The <i>vimana</i> is devoid of decoration except the <i>udyotasimha</i> at the center of <i>rahapagas</i> in the <i>gandi</i> . The <i>parsvadevata</i> niches contain images of Kali, Varahi and one unidentified image. In the additional hall in front of the <i>jagamohana</i> the stories of Mahisasuramardini, Umamaheswara, Savitri-satyaban, Krisna lila etc are recently depicted.
Interiors :	On either side of the doorjambs there are niches, those house the images of Dasamahavidya in their terrific form.
Movable Collections : * Any Other (specify) :	Nil The temple is <i>triratha</i> on plan .
10. Construction Technology	
Structural System	: Rekha vimana and pidha jagamohana of Kalingan order.
Building Techniques Material of Construction	: Ashlar masonry with lime mortar.: Light grey sand stone.
11. Condition Assessment	
In General Good /	Fair Good
	Sign of Deterioration Serious Deterioration Danger of Disappearance
In Brief (Attach extra sheet if nee	cessary):

The temple is facing now the problem of encroachment, which conceal the temple from out

12. Threats to	the Proper	ty							_
X x	x x	x	Natural Negligend Vandalish Urban Pre	า	x	x	x	X	
			TION III: RE						
13. Reference	e Sources (p	ublished ar	nd unpublish	ed textua	al details	s)			
14. Photograp	ohs								
			(Attach list	as in pag	ge 6, in	case of	multiple	photograp	hs)
Photo Referen	nce	: :							
15. Audio / Vi	deo								
			(R	elated to	rituals,	/ perforn	nance, /	festivals e	tc.
Reference DESCRIPTION	N	:							
16. Maps/Plar	ns/Drawings	i							
17. Listers									
NAME :	B. B. Satpa	athy	NAM	IE :					
18.Reviewers									
NAME : COMMENTS	Dr. S. Prad	han	NAME COMI	E: MENTS:					