

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/BKN-006

1. Name	SECTION I : IDENTIFICATION
Present Past Other Name (if any): 2. Location	: Shree Raj Ratan Bihariji Mandir : :
LONGITUDE 74 ⁰ 12 ['] E	LATITUDE 29 ⁰ 03' N
Address	Ratan Jee Mandir, Bikaner
Approach	 : Village (village code) Post : Bikaner District: Bikaner State : Rajasthan PIN: 334001 : The Temple is situated at Bikaner City. It is 2 km away from Bikaner Bus Stand. It is well connected by regular bus services.

3. Property Type

Bui	ildings	Religious structures	Other Structures
Palace	\checkmark	Temple	Wall
Fort		Mosque	Gateway
Citadel		Minar	Pillar
Govt. buil	ding	Church	Others (specify)
Railway s	tation	Monastery	
Defence b	ouilding	Stupa	
Industrial	building	Tomb, Mausoleum	
Other pub	olic buildings		
Residentia	al building		
Engineer	•	pen space and related tructures	Note: It is a double story temple. The façade of the temple is highly
Engineer Bridge	-		
	-	tructures	The façade of the temple is highly impressive. It has foliated arch gateway. It can be approached
Bridge Tunnel	-	ructures Public square	The façade of the temple is highly impressive. It has foliated arch gateway. It can be approached through flight of steps. The upper
Bridge Tunnel		r uctures Public square Park or garden	The façade of the temple is highly impressive. It has foliated arch gateway. It can be approached through flight of steps. The upper portion has beautiful canopied
Bridge Tunnel		Public square Park or garden Graveyard	The façade of the temple is highly impressive. It has foliated arch gateway. It can be approached through flight of steps. The upper portion has beautiful canopied chhatri surrounded by extended
Bridge Tunnel		Public square Park or garden Graveyard Baolis, Well	The façade of the temple is highly impressive. It has foliated arch gateway. It can be approached through flight of steps. The upper portion has beautiful canopied chhatri surrounded by extended ornated chhajja. The chajja is
Bridge Tunnel		ructures Public square Park or garden Graveyard Baolis, Well Tank	The façade of the temple is highly impressive. It has foliated arch gateway. It can be approached through flight of steps. The upper portion has beautiful canopied chhatri surrounded by extended ornated chhajja. The chajja is supported by carved stone
Bridge Tunnel		ructures Public square Park or garden Graveyard Baolis, Well Tank	The façade of the temple is highly impressive. It has foliated arch gateway. It can be approached through flight of steps. The upper portion has beautiful canopied chhatri surrounded by extended ornated chhajja. The chajja is

4. Property Use ABANDONED / IN USE : In Use Present Religious 2 Past : Religious 5. Age (Source) 17th Century AD PERIOD : YEARS : Precise date of Construction 2 Completion : Subsequent changes : **Destruction / Demolition** : 6. Ownership / Level of Protection SINGLE /MULTIPLE : **Public** : Archaeological Survey of : State Archeology Department India / State Archaeology Department / Any Other (Please specify) Private 2 Any other (Please specify) : Name : Address : Phone ÷ 7. Association WITH EVENTS In History : In Rituals : In Building Construction : Any other (specify) Living temple : WITH PERSONS Patron : **Architect / Engineer** 2 Any other (specify) : 8. Statement of Significance Architectural

Archaeological Historical Religious Any other (specify)

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features			
Context Urban / Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary) Urban	
			Stand in Isolation Integral part of a Landscape / Street / Complex
•	Quantification Area Dimension (L x B x H)	:	(m / cm/ feet / inch)
	Number of Blocks Number of Storys	:	01 02
•	Spatial Organization Orientation Plan Allocation of Spaces	:	The Temple is oriented East/West and faces the east
•	RCHITECTURAL STYLE Ornamentation Exteriors Interiors Movable Collections Ny Other (specify)	:	Highly impressive façade with beautiful chhatri

10. Construction Technology

Structural System Building Techniques	:	Indo-Persian Arcuate
Material of Construction	:	Stone.

11. Condition Assessment

In General	Good / Fair Good	

Sign of Deterioration
 Serious Deterioration
 Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Well maintained.

12. Threats to the Property

✓ Natural
 Negligence
 Vandalism
 Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	· · · · · · · · · · · · · · · · · · ·
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS