

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/BKN-009

1. Name	SECTION I : IDENTIFICATION
Present Past Other Name (if any): 2. Location	: Daulat Pol :
LONGITUDE 74 ⁰ 12 ['] E	LATITUDE 29 ⁰ 03' N
Address	Daulat Pol, Junagarh, Bikaner
	: Village (village code) Post : Bikaner State : Rajasthan District: Bikaner PIN: 334001
Approach	: The Gateway is situated at Bikaner City. It is 1 km away from Bikaner Bus Stand. It is well connected by regular bus services.

3. Property Type

Buildings		Religious structures	Other Structures		
	Palace	Temple	Wall		
	Fort	Mosque	✓ Gateway		
	Citadel	Minar	Pillar		
	Govt. building	Church	Others (specify)		
	Railway station	Monastery			
	Defence building	Stupa			
	Industrial building	Tomb, Mausoleum			
	Other public buildings				
	Residential building				
	Engineering structure	Open space and related structures	Note: This is a beautiful gateway.		
		structures	It has pointed arch three bays		
	<i>Engineering structure</i> Bridge Tunnel	structures Public square	с ,		
	Bridge	structures	It has pointed arch three bays openings. The name of the pol is		
	Bridge Tunnel	structures Public square Park or garden	It has pointed arch three bays openings. The name of the pol is written on the façade. There are medallion on the spandrel. The upper portion has double storey		
	Bridge Tunnel	structures Public square Park or garden Graveyard	It has pointed arch three bays openings. The name of the pol is written on the façade. There are medallion on the spandrel. The upper portion has double storey palatial building for residence.		
	Bridge Tunnel	structures Public square Park or garden Graveyard Baolis, Well	It has pointed arch three bays openings. The name of the pol is written on the façade. There are medallion on the spandrel. The upper portion has double storey palatial building for residence. The arrangement of jharokhas and		
	Bridge Tunnel	structures Public square Park or garden Graveyard Baolis, Well Tank	It has pointed arch three bays openings. The name of the pol is written on the façade. There are medallion on the spandrel. The upper portion has double storey palatial building for residence. The arrangement of jharokhas and areal window as well as beautiful		
	Bridge Tunnel	structures Public square Park or garden Graveyard Baolis, Well Tank	It has pointed arch three bays openings. The name of the pol is written on the façade. There are medallion on the spandrel. The upper portion has double storey palatial building for residence. The arrangement of jharokhas and		

4. Property Use ABANDONED / IN USE : In use Present Gateway : Past : Gateway 5. Age (Source) 17th Century AD PERIOD : YEARS : Precise date of Construction 2 Completion : Subsequent changes : **Destruction / Demolition** : 6. Ownership / Level of Protection SINGLE /MULTIPLE : **Public** : Archaeological Survey of : State Archaeology Department India / State Archaeology Department / Any Other (Please specify) Private 2 Any other (Please specify) : Name 2 Address : Phone ÷ 7. Association WITH EVENTS In History : In Rituals 2 In Building Construction : Any other (specify) : WITH PERSONS Patron 2 **Architect / Engineer** 2 Any other (specify) : 8. Statement of Significance Architectural Archaeological Historical Religious Any other (specify)

SECTION II: DESCRIPTION

	Context Urban / Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary) Urban
	Surroundings		Stand in Isolation Integral part of a Landscape / Street / Complex
•	Quantification Area Dimension (L x B x H)	:	(m / om / foot / in oh
	Number of Blocks Number of Storys	:	(m / cm/ feet / inch 01 01
•	Spatial Organization Orientation	:	The Gateway is oriented North/South and faces the North
	Plan Allocation of Spaces	:	
•	RCHITECTURAL STYLE Ornamentation Exteriors Interiors Movable Collections by Other (specify)	:	Pointed arch Gateway
10	. Construction Technology		
	Structural System Building Techniques Material of Construction	:	Indo-Persian Arcuate Stone.

11. Condition Assessment

Good / Fair Good

Sign of Deterioration

Serious Deterioration

Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Well maintained

12. Threats to the Property

✓ Natural
Negligence
Vandalism
Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS