

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS


Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/BKN-016

1. Name	SECTION I : IDENTIFICATION
Present Past Other Name (if any): 2. Location	: Rup Singh ki Chhatri :
LONGITUDE 74 [°] 12 [°] E	LATITUDE 29 ⁰ 03' N
Address	Junagarh, Bikaner
Approach	 : Village (village code) Post : Bikaner District: Bikaner State : Rajasthan PIN: 334001 : The Chhatri is situated at Bikaner City. It is 1 km away from Bikaner Bus Stand. It is well connected by regular bus services.

3. Property Type



4. Property Use ABANDONED / IN USE : Abandoned Present Memorial 2 Memorial Past • 5. Age (Source) 18th Century AD PERIOD : YEARS : Precise date of Construction 2 Completion : Subsequent changes : **Destruction / Demolition** : 6. Ownership / Level of Protection SINGLE /MULTIPLE : **Public** : Archaeological Survey of : India / State Archaeology Department / Any Other (Please specify) Private 2 Any other (Please specify) : Name 2 Address : Phone 2 7. Association WITH EVENTS In History : In Rituals 2 In Building Construction : Any other (specify) : WITH PERSONS Patron 2 **Architect / Engineer** 2 Any other (specify) : 8. Statement of Significance Architectural

Archaeological Historical Religious Any other (specify)

SECTION II: DESCRIPTION

9.	9. Physical Description and Decorative Features				
U	Context Urban / Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary) Urban		
	-		Stand in Isolation Integral part of a Landscape / Street / Complex		
•	Quantification Area Dimension (L x B x H) Number of Blocks	:	(m / cm/ feet / inch) 01		
•	Number of Storys Spatial Organization Orientation	:	01 The Chhatri is oriented East/West and faces the East		
<u>AI</u>	Plan Allocation of Spaces RCHITECTURAL STYLE	:			
• Aı	Ornamentation Exteriors Interiors Movable Collections by Other (specify)	:	Canopied chhatri		

10. Construction Technology

Structural System Building Techniques	:	Indo-Persian Arcuate
Material of Construction	:	Stone

11. Condition Assessment

In General

Good / Fair Good

Sign of Deterioration Serious Deterioration Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Blackening, deposition of dust and dirt.

12. Threats to the Property

✓ Natural
 Negligence
 Vandalism
 Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS