


INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/BKN-054

1. Name	SECTION I : IDENTIFICATION
Present Past Other Name (if any):	: Ganesh Pol :
2. Location	
LONGITUDE 74 ⁰ 12 ['] E	LATITUDE 29 ⁰ 03 ['] N
Address	Lal Garh Palace, Bikaner
	: Village (village code) Post : Bikaner State : Rajasthan PIN: 334001
Approach	: The Gateway is situated at Bikaner City. It is 1 k.m. away from Bikaner bus stand. It is well connected by regular bus services.
3. Property Type	



4. Property Use

	ABANDONED / IN USE : In use
Present	:
Past	:
5. Age (Source)	
PERIOD	: 17 th Century A.D.
YEARS	:
Precise date of Construction	:
Completion	:
Subsequent changes	:
Destruction / Demolition	:
6. Ownership / Level of Protection	on
	SINGLE /MULTIPLE :
Public : Archaeological Survey of	:
India / State Archaeology	
Department / Any Other (Please	
specify)	
Private	:
Any other (Please specify)	:
Name	:
Address	:
Phone	:
7. Association	
WITH EVENTS	
In History	:
In Rituals	:
In Building Construction	:
Any other (specify)	:
WITH PERSONS	
Patron	:
Architect / Engineer	:
Any other (specify)	:
8. Statement of Significance	
Architectural	It looks like a gateway to the main complex
Archaeological	
Historical	
Religious	
Any other (specify)	

SECTION II: DESCRIPTION

9.	9. Physical Description and Decorative Features					
 Context Urban / Rural Setting Surroundings 			* Drawings (Attach extra sheet if necessary) Urban			
	Surroundings		Stand in Isolation Integral part of a Landscape / Street / Complex			
•	Quantification Area Dimension (L x B x H)	:	(m / cm/ feet / inch)			
	Number of Blocks Number of Storys	:	01 02			
•	Spatial Organization Orientation Plan Allocation of Spaces	:	The Gateway is oriented East-West and faces the West			
•	RCHITECTURAL STYLE Ornamentation Exteriors Interiors Movable Collections by Other (specify)	:	Multiple arched gateway			

10. Construction Technology

Building Techniques		Indo-persian system Arcuate Sandstone
---------------------	--	---

11. Condition Assessment

In General	Good / Fair Good	
	0000	

Sign of Deterioration Serious Deterioration Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Well maintained.

12. Threats to the Property

Natural Negligence Vandalism Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS