

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS


Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/BKN-075

1. Name	SECTION I : IDENTIFICATION		
Present Past Other Name (if any): 2. Location	: Shree Chand Kanwar jee ki Chhatri :		
LONGITUDE 74 ⁰ 12 ['] E	LATITUDE 29 ⁰ 03 [°] N		
Address	Devi Kund Sagar, Bikaner		
	: Village (village code) Post : Bikaner State : Rajasthan PIN: 334001		
Approach	: The Chhatri is situated at Bikaner City. It is 7 k.m. away from Bikaner bus stand. It is well connected by regular bus services.		

3. Property Type



4. Property Use

	ABANDONED / IN USE : Abandoned
Present Past	: Memorial : Memorial
5. Age (Source)	
PERIOD YEARS Precise date of Construction Completion Subsequent changes Destruction / Demolition	16 th Century A.D.
6. Ownership / Level of Protection	
Public : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify) Private Any other (Please specify) Name Address Phone 7. Association	SINGLE /MULTIPLE : : : : :
 WITH EVENTS In History In Rituals In Building Construction Any other (specify) WITH PERSONS Patron Architect / Engineer Any other (specify) 	Memorial
8. Statement of Significance Architectural Archaeological Historical Definition	Domical superstructure
Religious Any other (specify)	

2

SECTION II: DESCRIPTION

9.	9. Physical Description and Decorative Features				
•	Context Urban / Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary) Urban Stand in Isolation Integral part of a Landscape / Street / Complex		
•	Quantification Area Dimension (L x B x H) Number of Blocks Number of Storys	:	(m / cm/ feet / inch) 01 01		
•	Spatial Organization Orientation Plan Allocation of Spaces	:	The Chhatri is oriented East-West and faces the West		
•	RCHITECTURAL STYLE Ornamentation Exteriors Interiors Movable Collections by Other (specify)		Canopied chhatri, foliated arch, fluted column.		

10. Construction Technology

Structural System Building Techniques	:	Indo-Persian Arcuate system
Material of Construction	:	Stone and plaster

11. Condition Assessment

In General	Good / Fair	
	Good	

Sign of Deterioration Serious Deterioration Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Dust and dirt deposition

12. Threats to the Property

Natural Negligence Vandalism Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS