

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS


Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/BKN-085

1. Name	SECTION I : IDENTIFICATION
Present Past Other Name (if any): 2. Location	Lal Singh ki Chhatri
LONGITUDE 74 [°] 12 [°] E	LATITUDE 29 ⁰ 03 [°] N
Address	Devi Kund Sagar, Bikaner
	: Village (village code) Post : Bikaner State : Rajasthan PIN: 334001
Approach	: The Chhatri is situated at Bikaner City. It is 7 k.m. away from Bikaner bus stand. It is well connected by regular bus services.

3. Property Type



4. Property Use

		ABANDONED / IN USE : Abandoned
Present	:	Memorial
Past	:	Memorial
5. Age (Source)		
PERIOD	:	19 th Century A.D.
YEARS	:	
Precise date of Construction	:	
Completion	:	
Subsequent changes	:	
Destruction / Demolition	:	
6. Ownership / Level of Protection	on	
-		SINGLE /MULTIPLE :
Public : Archaeological Survey of	:	
India / State Archaeology	•	
Department / Any Other (Please		
specify)		
Private	:	
Any other (Please specify)	:	
Name	:	
Address	:	
Phone	:	
7. Association		
WITH EVENTS		
In History	:	Chhatri
In Rituals	:	
In Building Construction	:	
Any other (specify)	:	
WITH PERSONS		
Patron	:	
Architect / Engineer	:	
Any other (specify)	:	
9 Statement of Significance		
8. Statement of Significance		
Architectural	Do	omical superstructure

Archaeological Historical Religious Any other (specify)

SECTION II: DESCRIPTION

•	Context Urban / Rural Setting		 * Drawings (Attach extra sheet if necessary) Rural Setting
	Surroundings		Stand in Isolation Integral part of a Landscape / Street / Complex
•	Quantification Area Dimension (L x B x H)	:	(m/om/fact/inch
	Number of Blocks Number of Storys	:	(m / cm/ feet / inch 01 01
•	Spatial Organization Orientation Plan Allocation of Spaces	:	The Chhatri is oriented East-West and faces the West
<u>AF</u>	RCHITECTURAL STYLE Ornamentation		
•	Exteriors	:	Oblong Chhatri, Canopied chhatri, foliated arch, fluted column.
	Interiors Movable Collections	:	
Ar	ny Other (specify)	:	

10. Construction Technology

Structural System	:	Indo-Persian
Building Techniques	:	Arcuate system
Material of Construction	:	Stone and plaster

11. Condition Assessment

In	General

Good / Fair Good

Sign of Deterioration

Serious Deterioration

Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Blackening of surface

12. Threats to the Property

Natural Negligence Vandalism Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS