

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/BKN-102

1. Name	SECTION I : IDENTIFICATION
Present Past Other Name (if any):	Deep Kanwar ki Chhatri
2. Location	
LONGITUDE 74 ⁰ 12 ['] E	LATITUDE 29 ⁰ 03' N
Address	Devi Kund Sagar, Bikaner
	: Village (village code) Post : Bikaner District: Bikaner State : Rajasthan PIN: 334001
Approach	 The Chhatri is situated at Bikaner City. It is 7 km away from Bikaner Bus Stand. It is well connected by regular bus services.
3. Property Type	

3. Property Type

 Buildings		Religious structures	Oth	ner Structures
Palace		Temple	Wall	
Fort		Mosque	Gatewa	Ŋ
Citadel		Minar	Pillar	
Govt. building		Church	✓ Others	(specify)
Railway station		Monastery	Chhatr	i
Defence building		Stupa		
Industrial building		Tomb, Mausoleum		
Other public buildings		-		
Residential building				
Engineering structure	-	pen space and related		is the chhatri of Deep
	-	ructures	Kanwar. It	had been made in 31
Bridge	-	r uctures Public square	Kanwar. It October 18	had been made in 31 325. It has ribbed
Bridge Tunnel	-	r uctures Public square Park or garden	Kanwar. It October 18 domical	had been made in 31 325. It has ribbed superstructure with
Bridge	-	r uctures Public square Park or garden Graveyard	Kanwar. It October 18 domical pinnacle.	had been made in 31 325. It has ribbed superstructure with It is made up of
Bridge Tunnel	-	r uctures Public square Park or garden Graveyard Baolis, Well	Kanwar. It October 18 domical pinnacle. elevated p	had been made in 31 325. It has ribbed superstructure with
Bridge Tunnel	-	ructures Public square Park or garden Graveyard Baolis, Well Tank	Kanwar. It October 18 domical pinnacle. elevated p decorated p	had been made in 31 325. It has ribbed superstructure with It is made up of platform which has
Bridge Tunnel	-	r uctures Public square Park or garden Graveyard Baolis, Well	Kanwar. It October 18 domical pinnacle. elevated p decorated p column a	had been made in 31 325. It has ribbed superstructure with It is made up of platform which has platform. It has fluted
Bridge Tunnel	-	ructures Public square Park or garden Graveyard Baolis, Well Tank	Kanwar. It October 18 domical pinnacle. elevated p decorated p column au	had been made in 31 325. It has ribbed superstructure with It is made up of platform which has platform. It has fluted nd foliated arches.

4. Property Use ABANDONED / IN USE : Abandoned Present Memorial 2 Memorial Past • 5. Age (Source) 19th Century AD PERIOD 2 YEARS 2 Precise date of Construction 2 Completion : Subsequent changes : **Destruction / Demolition** : 6. Ownership / Level of Protection SINGLE /MULTIPLE : **Public** : Archaeological Survey of : India / State Archaeology Department / Any Other (Please specify) Private 2 Any other (Please specify) : Name 2 Address 2 Phone ÷ 7. Association WITH EVENTS In History : In Rituals 2 In Building Construction : Any other (specify) : WITH PERSONS Patron : Memorial **Architect / Engineer** : Any other (specify) : 8. Statement of Significance Domical superstructure

Architectural Archaeological Historical Religious Any other (specify)

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features			
 Context Urban / Rural Setting Surroundings 		* Drawings (Attach extra sheet if necessary) Rural Stand in Isolation Integral part of a Landscape / Street / Complex	
 Quantification Area Dimension (L x B x H) Number of Blocks Number of Storys 	:	(m / cm/ feet / inch) 01 01	
 Spatial Organization Orientation Plan Allocation of Spaces 	:	The Chhatri is oriented North/South and faces the South	
ARCHITECTURAL STYLE • Ornamentation Exteriors Interiors Movable Collections Any Other (specify)	: : : : : : : : : : : : : : : : : : : :	Canopied chhatri, fluted column, , foliated arches	

10. Construction Technology

Structural System	:	Indo-Persian
Building Techniques	:	Trabeate system
Material of Construction	:	Stone and plaster

11. Condition Assessment

In General	Good / Fair	
	Good	

Sign of Deterioration Serious Deterioration Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Blackening of surface

12. Threats to the Property

Natural Negligence Vandalism Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	· · · · · · · · · · · · · · · · · · ·
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS