

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS


Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/BKN-122

1. Name	SECTION I : IDENTIFICATION		
Present Past Other Name (if any): 2. Location	: Arajun Singh ki Chhatri :		
LONGITUDE 74 ⁰ 12 ['] E	LATITUDE 29 ⁰ 03' N		
Address	Devi Kund Sagar, Bikaner		
	: Village (village code) Sagar Post : Bikaner District: Bikaner State : Rajasthan PIN: 334001		
Approach	 The Chhatri is situated at Bikaner City. It is 7 km away from Bikaner Bus Stand. It is well connected by regular bus services. 		

3. Property Type



4. Property Use ABANDONED / IN USE : Abandoned Present Memorial 2 Memorial Past • 5. Age (Source) 17th Century AD PERIOD : YEARS : Precise date of Construction 2 Completion : Subsequent changes : **Destruction / Demolition** : 6. Ownership / Level of Protection SINGLE /MULTIPLE : **Public** : Archaeological Survey of : India / State Archaeology Department / Any Other (Please specify) Private 2 Any other (Please specify) : Name 2 Address 2 Phone ÷ 7. Association WITH EVENTS In History : In Rituals 2 In Building Construction : Any other (specify) : WITH PERSONS Patron : Memorial **Architect / Engineer** : Any other (specify) : 8. Statement of Significance Architectural Domical superstructure

Architectural Archaeological Historical Religious Any other (specify)

SECTION II: DESCRIPTION

9.	9. Physical Description and Decorative Features				
•	Context Urban / Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary) Rural Stand in Isolation Integral part of a Landscape / Street / Complex		
•	Quantification Area Dimension (L x B x H) Number of Blocks Number of Storys	:	(m / cm/ feet / inch) 01 01		
•	Spatial Organization Orientation Plan Allocation of Spaces	:	The Chhatri is oriented North/South and faces the South		
•	RCHITECTURAL STYLE Ornamentation Exteriors Interiors Movable Collections by Other (specify)		Canopied chhatri		

10. Construction Technology

Structural System	:	Indo-Persian
Building Techniques	:	Trabeate system
Material of Construction	:	Stone and plaster

11. Condition Assessment

In General	Good / Fair	
	Good	

Sign of Deterioration Serious Deterioration Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Dust and Dirt Deposition

12. Threats to the Property

Natural Negligence Vandalism Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS