


INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/BKN-194

	SECTION I : IDENTIFICATION
1. Name	
Present Past Other Name (if any):	: Ramlal ji ki Haveli :
2. Location	
LONGITUDE 74 ⁰ 12 ['] E	LATITUDE 29 ⁰ 03 ['] N
Address	Jail Road, Bikaner
	: Village (village code) Post : Bikaner State : Rajasthan PIN: 334001
Approach	: The Haveli is situated at Bikaner City. It is 4 k.m. away from Bikaner bus stand It is well connected by regular bus services.
3. Property Type	



4. Property Use

. /	ABANDONED / IN USE : Abandoned
Present Past	: Residential
5. Age (Source)	
PERIOD	: 18 th Century A.D.
YEARS	:
Precise date of Construction	:
Completion	:
Subsequent changes	:
Destruction / Demolition	:
6. Ownership / Level of Protection	on
	SINGLE /MULTIPLE :
Public : Archaeological Survey of	:
India / State Archaeology	
Department / Any Other (Please	
specify)	
Private	:
Any other (Please specify)	
Name Address	
Phone	
FIIOIle	-
7. Association	
WITH EVENTS	
In History	:
In Rituals	:
In Building Construction	:
Any other (specify)	:
WITH PERSONS	
Patron	: Ramlal ji ki Haveli
Architect / Engineer Any other (specify)	
Any other (specify)	
8. Statement of Significance	
Architectural	Foliated arch

Architectural Archaeological Historical Religious Any other (specify)

SECTION II: DESCRIPTION

9.	9. Physical Description and Decorative Features				
•	Context Urban / Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary) Urban Stand in Isolation Integral part of a Landscape / Street / Complex		
•	Quantification Area Dimension (L x B x H) Number of Blocks Number of Storys	:	(m / cm/ feet / inch 02	ר)	
•	Spatial Organization Orientation Plan Allocation of Spaces	:	The Haveli is oriented East-West and faces the West		
•	RCHITECTURAL STYLE Ornamentation Exteriors Interiors Movable Collections Ny Other (specify)		Foliated arch, Jharokha		

10. Construction Technology

Structural System	:	Indo-Persian
Building Techniques	:	Trabeate system
Material of Construction	:	Stone & plaster

11. Condition Assessment

In General	Good / Fair	
	Good	

Sign of DeteriorationSerious DeteriorationDanger of Disappearance

In Brief (Attach extra sheet if necessary):

Dust and dirt deposition

12. Threats to the Property

Natural Negligence Vandalism Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS