

**INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS** 

Janpath, New Delhi -110 001, www.ignca.gov.in

## Documentation format for Archaeological / Heritage Sites / Monuments

#### Serial No.: RJ/BKN-213

	SECTION I: IDENTIFICATION	
1. Name		
Present Past Other Name (if any):	Chauth Mata jee Mandir	
2. Location		
<b>LONGITUDE</b> 74 <sup>0</sup> 12 <sup>'</sup> E	LATITUDE 29 <sup>0</sup> 03 <sup>'</sup> N	
Address	Goga Gate Chauraha, Bikaner	
	: Village (village code) Post : Bikaner State : Rajasthan PIN: 334001	
Approach	: The Temple is situated at Bikaner City. It is 5 k.m. away from Bikaner Bus Stand. It is well connected by regular bus services.	
2 Broporty Typo		

#### 3. Property Type

Buildings		Religious structures		Other Structures
Palace	$\checkmark$	Temple		Wall
Fort		Mosque		Gateway
Citadel		Minar		Pillar
Govt. building		Church		Others (specify)
Railway station		Monastery		
Defence building		Stupa		
Industrial building		Tomb, Mausoleum		
Other public buildings		_		
Residential building				
Engineering structure	-	oen space and related ructures		te: This is the temple of Chauth ta. It is made up on elevated
 Engineering structure	-	-	ma	te: This is the temple of Chauth ta. It is made up on elevated tform. It has domical
	-	ructures	ma pla	ta. It is made up on elevated
Bridge	-	r <b>uctures</b> Public square	ma pla sup it.	ta. It is made up on elevated tform. It has domical perstructure with pinnacle over It has foliated arch opening and
Bridge Tunnel	-	r <b>uctures</b> Public square Park or garden	ma pla sup it. spa	ta. It is made up on elevated tform. It has domical perstructure with pinnacle over It has foliated arch opening and andrel is decorated with
Bridge Tunnel	-	r <b>uctures</b> Public square Park or garden Graveyard	ma pla sup it. spa me	ta. It is made up on elevated tform. It has domical perstructure with pinnacle over It has foliated arch opening and andrel is decorated with dallion. Wall of the temple are
Bridge Tunnel	-	Public square Park or garden Graveyard Baolis, Well	ma pla sup it. spa me dec	ta. It is made up on elevated tform. It has domical perstructure with pinnacle over It has foliated arch opening and andrel is decorated with dallion. Wall of the temple are corated with lattice pattern and
Bridge Tunnel	-	Public square Public square Park or garden Graveyard Baolis, Well Tank	ma pla sup it. spa dec alco	ta. It is made up on elevated tform. It has domical perstructure with pinnacle over It has foliated arch opening and andrel is decorated with dallion. Wall of the temple are

#### 4. Property Use ABANDONED / IN USE : In use Present Religious 2 Religious Past : 5. Age (Source) 17<sup>th</sup> Century A.D. PERIOD : YEARS : Precise date of Construction 2 Completion : Subsequent changes : **Destruction / Demolition** : 6. Ownership / Level of Protection SINGLE /MULTIPLE : **Public** : Archaeological Survey of : India / State Archaeology Department / Any Other (Please specify) Private 2 Any other (Please specify) : Name 2 Address 2 Phone ÷ 7. Association WITH EVENTS In History 2 In Rituals Temple : In Building Construction : Any other (specify) : WITH PERSONS Patron 2 **Architect / Engineer** 2 Any other (specify) : 8. Statement of Significance Architectural Domical superstructure Archaeological Historical Religious

Any other (specify)

SECTION II: DESCRI
--------------------

9.	9. Physical Description and Decorative Features			
•	Context Urban / Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary) Urban Stand in Isolation Integral part of a Landscape / Street / Complex	
•	Quantification Area Dimension (L x B x H) Number of Blocks Number of Storys	:	(m / cm/ feet / inch) 01 01	
•	<b>Spatial Organization</b> Orientation Plan Allocation of Spaces	:	The Chhatri is oriented East-West and faces the East	
•	<b>RCHITECTURAL STYLE</b> <b>Ornamentation</b> Exteriors Interiors Movable Collections <b>Ny Other</b> (specify)	: : : : : : : : : : : : : : : : : : : :	Canopied chhatri, foliated arch, medallion, alcoves	

## **10. Construction Technology**

Structural System	: Indo-Persian
Building Techniques	: Arcuate system
Material of Construction	: Stone and plaster

#### **11. Condition Assessment**

#### In General

#### Good / Fair Good

Sign of Deterioration Serious Deterioration Danger of Disappearance

#### In Brief (Attach extra sheet if necessary):

Blackening of surface, dust and dirt deposition

## 12. Threats to the Property

Natural Negligence Vandalism Urban Pressures

# SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS