

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/BKN-253

1. Name	SECTION I : IDENTIFICATION	
Present Past Other Name (if any): 2. Location	: Shree Ganga jee ka Mandir :	
LONGITUDE 74 ⁰ 12 ['] E	LATITUDE 29 ⁰ 03 ['] N	
Address	Kolayat Tirth, Bikaner	
	: Village (village code) Kolayat Post : Kolayat District: Bikaner State : Rajasthan PIN: 334502	
Approach	 The Temple is situated at Kolayat in Bikaner. It is 50 k.m. away from Bikaner District. It is well connected by regular bus services. 	

3. Property Type

 Buildings		Religious structures		Other Structures
Palace	\checkmark	Temple		Wall
Fort		Mosque		Gateway
Citadel		Minar		Pillar
Govt. building		Church		Others (specify)
 Railway station		Monastery		
 Defence building		Stupa		
 Industrial building		Tomb, Mausoleum		
Other public buildings				
Residential building				
Engineering structure	-	pen space and related		e: This temple is dedicated to
 	-	ructures	Gar	nga jee. It has ribbed domical
Bridge	-	r uctures Public square	Gar sup	nga jee. It has ribbed domical erstructure. This temple is
Bridge Tunnel	-	r uctures Public square Park or garden	Gar sup mac	nga jee. It has ribbed domical erstructure. This temple is de up on highly elevated
Bridge	-	ructures Public square Park or garden Graveyard	Gar sup mac plat	nga jee. It has ribbed domical erstructure. This temple is de up on highly elevated form with raised staircases. At
Bridge Tunnel	-	r uctures Public square Park or garden Graveyard Baolis, Well	Gar sup mac plat entr	nga jee. It has ribbed domical erstructure. This temple is de up on highly elevated form with raised staircases. At ance there is an oblong
Bridge Tunnel	-	Fuctures Public square Park or garden Graveyard Baolis, Well Tank	Gar sup mac plat entr chh	nga jee. It has ribbed domical erstructure. This temple is de up on highly elevated form with raised staircases. At ance there is an oblong atri and foliated arch opening.
Bridge Tunnel	-	r uctures Public square Park or garden Graveyard Baolis, Well	Gar sup mac plat entr chha Insid	nga jee. It has ribbed domical erstructure. This temple is de up on highly elevated form with raised staircases. At ance there is an oblong atri and foliated arch opening. de there are fluted column.
Bridge Tunnel	-	Fuctures Public square Park or garden Graveyard Baolis, Well Tank	Gar sup mac plat entr chh Insid San	nga jee. It has ribbed domical erstructure. This temple is de up on highly elevated form with raised staircases. At ance there is an oblong atri and foliated arch opening.

4. Property Use ABANDONED / IN USE : In use Present Religious : Religious Past : 5. Age (Source) 18th Century A.D. PERIOD 2 YEARS : Precise date of Construction 2 Completion : Subsequent changes : **Destruction / Demolition** : 6. Ownership / Level of Protection SINGLE /MULTIPLE : **Public** : Archaeological Survey of : India / State Archaeology Department / Any Other (Please specify) Private 2 Any other (Please specify) : Name 2 Address 2 Phone ÷ 7. Association WITH EVENTS In History : In Rituals : In Building Construction : Any other (specify) : WITH PERSONS Patron : Temple **Architect / Engineer** : Any other (specify) : 8. Statement of Significance Architectural Domical superstructure

Architectural Archaeological Historical Religious Any other (specify)

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features			
•	Context Urban / Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary) Urban Stand in Isolation Integral part of a Landscape / Street / Complex
•	Quantification Area Dimension (L x B x H) Number of Blocks Number of Storys	: : :	(m / cm/ feet / inch) 01 01
•	Spatial Organization Orientation Plan Allocation of Spaces	:	The Temple is oriented North-South and faces the North
•	RCHITECTURAL STYLE Ornamentation Exteriors Interiors Movable Collections by Other (specify)		Canopied & Oblong Chhatri, Foliated arch Foliated arch, Fluted column

10. Construction Technology

Structural System Building Techniques	:	Indo-Persian Arcuate system
Material of Construction	:	Stone and Plaster

11. Condition Assessment

In General	Good / Fair	
	Good	

Sign of Deterioration Serious Deterioration Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Blackening of surface

12. Threats to the Property

Natural Negligence Vandalism Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS