

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/BKN-283

1. Name	SECTION I : IDENTIFICATION
Present Past Other Name (if any): 2. Location	Shree Karani Mata Mandir
LONGITUDE 74 ⁰ 12 ['] E	LATITUDE 29 ⁰ 03 [°] N
Address	Deshnoke, Bikaner
	: Village (village code) Post : Bikaner State : Rajasthan PIN: 334502
Approach	 The Temple is situated at Deshnoke in Bikaner District. It is 50 k.m. away from Bikaner bus stand It is well connected by regular bus services.

3. Property Type

Buildings		Religious structures	Other Structures		
	Palace	✓ Temple	Wall		
	Fort	Mosque	Gateway		
	Citadel	Minar	Pillar		
	Govt. building	Church	Others (specify)		
	Railway station	Monastery			
	Defence building	Stupa			
	Industrial building	Tomb, Mausoleum			
	Other public buildings				
	Residential building				
	Engineering structure	Open space and related structures	Note: This temple is dedicated to Karani Mata. It is a highly		
		structures	Note: This temple is dedicated to Karani Mata. It is a highly decorated temple. At entrance the		
	Engineering structure Bridge Tunnel		Karani Mata. It is a highly		
	Bridge	structures Public square	Karani Mata. It is a highly decorated temple. At entrance the walls of the temple are engraved. It has circular arch opening and		
	Bridge Tunnel	structures Public square Park or garden	Karani Mata. It is a highly decorated temple. At entrance the walls of the temple are engraved. It has circular arch opening and spandrel is decorated with fringe		
	Bridge Tunnel	structures Public square Park or garden Graveyard	Karani Mata. It is a highly decorated temple. At entrance the walls of the temple are engraved. It has circular arch opening and spandrel is decorated with fringe pattern. It has oblong chhatri and		
	Bridge Tunnel	structures Public square Park or garden Graveyard Baolis, Well	Karani Mata. It is a highly decorated temple. At entrance the walls of the temple are engraved. It has circular arch opening and spandrel is decorated with fringe pattern. It has oblong chhatri and having foliated arches and fluted		
	Bridge Tunnel	structures Public square Park or garden Graveyard Baolis, Well Tank	Karani Mata. It is a highly decorated temple. At entrance the walls of the temple are engraved. It has circular arch opening and spandrel is decorated with fringe pattern. It has oblong chhatri and having foliated arches and fluted column. Temple has ribbed		
	Bridge Tunnel	structures Public square Park or garden Graveyard Baolis, Well Tank	Karani Mata. It is a highly decorated temple. At entrance the walls of the temple are engraved. It has circular arch opening and spandrel is decorated with fringe pattern. It has oblong chhatri and having foliated arches and fluted		

4. Property Use ABANDONED / IN USE : In use Present Religious : Religious Past : 5. Age (Source) 17th Century A.D. PERIOD : YEARS : Precise date of Construction 2 Completion : Subsequent changes : **Destruction / Demolition** : 6. Ownership / Level of Protection SINGLE /MULTIPLE : **Public** : Archaeological Survey of : India / State Archaeology Department / Any Other (Please specify) Private 2 Any other (Please specify) : Name 2 Address : Phone ÷ 7. Association WITH EVENTS In History : In Rituals 2 In Building Construction : Any other (specify) : WITH PERSONS Patron 2 **Architect / Engineer** 2 Any other (specify) : 8. Statement of Significance Architectural Archaeological Historical Religious Any other (specify)

SECTION II: DESCRIPTION

•	Context Urban / Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary) Rural Setting	
			Stand in Isolation Integral part of a Landscape / Street / Complex	
•	Quantification Area Dimension (L x B x H)	:		
	Number of Blocks Number of Storys	:	(m / cm/ feet / inch 02	
•	Spatial Organization Orientation Plan Allocation of Spaces	:	The Temple is oriented East-West and faces the West	
•	CHITECTURAL STYLE Ornamentation Exteriors Interiors Movable Collections by Other (specify)	:		

Structural System		
Building Techniques		
Material of Construction		

11. Condition Assessment

In General

Good / Fair Good

:

Sign of Deterioration Serious Deterioration Danger of Disappearance

In Brief (Attach extra sheet if necessary):

12. Threats to the Property

Natural Negligence Vandalism Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS