

## INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

## **Documentation format for Archaeological / Heritage Sites / Monuments** Serial No.: RJ/BLW-039 **SECTION I: IDENTIFICATION** 1. Name Ram Bai Well Present Past Other Name (if any): 2. Location **LONGITUDE** 75°28'E LATITUDE 25°58'N Address Near Nilkanth Mahadev Mandir Ward Nor-4 Village (village code) Pur Post: Pur District: Bhilwara State: Rajasthan **PIN**: 311802 Approach district The Well is situated at Nilkanth Mahadev Mandir Pur in Bhilwara district. It is 10km away from Bhilwara bus stand. It is well connected by regular bus services. 3. Property Type Religious structures **Other Structures Buildings** Palace Temple Wall Mosque Fort Gateway Minar Pillar Citadel Church Govt. building Others (specify) Railway station Monastery Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Engineering structure Open space and related Note: It is an ancient well Paved structures with stone. It is a square in shape. Public square It has structure for fetching water. Bridge Tunnel Park or garden Other engineering structure Graveyard Baolis, Well Tank

Cave

4. Property Use		
		ABANDONED / √IN USE
Present Past	:	Drinking Water Drinking Water
5. Age (Source)		
PERIOD YEARS	:	19 <sup>th</sup> Century AD
Precise date of Construction Completion Subsequent changes Destruction / Demolition  6. Ownership / Level of Protection	: : : :	
	<u> </u>	SINGLE /MULTIPLE :
Public: Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)state Govt. Private Any other (Please specify) Name Address Phone 7. Association	: : : : : : : : : : : : : : : : : : : :	
WITH EVENTS     In History     In Rituals     In Building Construction     Any other (specify)      WITH PERSONS     Patron     Architect / Engineer     Any other (specify)  8. Statement of Significance	: : : : : : : : : : : : : : : : : : : :	Well with Circular ruined Platform.
Architectural Archaeological Historical Religious		

	Any other (specify)	:			
SECTION II: DESCRIPTION					
•	Physical Description and De Context Urban √/ Rural Setting Surroundings	cora	* Drawings (Attach extra sheet if necessary)  Stand in Isolation Integral part of a Landscape / Street / Complex		
•	Quantification Area Dimension (L x B x H)  Number of Blocks Number of Storys	: : : : : : : : : : : : : : : : : : : :	(m / cm/ feet / inch)		
•	Spatial Organization Orientation Plan Allocation of Spaces	: : : : : : : : : : : : : : : : : : : :	The Well is Oriented North/South and faces the South.		
• An	Ornamentation Exteriors Interiors Movable Collections by Other (specify)	: : : :	Denice for fetching water.		
10	. Construction Technology				
	Structural System Building Techniques Material of Construction	: : :	Square Well Stone, Plaster		

11. Condition Assessment					
In General	Good√ / Fair				
	Sign of Deterioration Serious Deterioration Danger of Disappearance				
In Brief (Attach extra sheet if necessary):					
The exterior wall is peeling off due to mainshrine and varied temperature. Also there is Staiwind discoloration of the stone layed for flooring.					
12. Threats to the Property					
	√ Natural				
	Negligence				
	√ Urban Pressures				

## **SECTION III:** REFERENCES

## 13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS