

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.:RJ/BLW-058

1. Name	SECTION I: IDENTIFICATION
Present Past Other Name (if any):	: Vishnu Ki Bawari :
2. Location	
LONGITUDE 75°28'E	LATITUDE 25°58'N
Address	Near Harijan Basti , Mandela road, Ward no 4 Pur
	: Village (village code)
	Post: PurDistrict: BhilwaraState: RajasthanPIN: 311802
Approach district	: The Bawari is situated near by Mandela road at pur in Bhilwara district. It is 10km away from Bhilwara bus stand. it well connected by regular bus services.
3. Property Type	
Buildings	Religious structures Other Structures
Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public buildings Residential building	Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum Wall Gateway Pillar Others (specify) Bawari
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structures Public square Park or garden Graveyard Baolis, Well Tank Cave Note: It is a rubble lined wall with built edges along the ground level on one of the sided there are two probably to hold the pully shaft. Also there are holes along these stone slabs.

4. Property Use	
	ABANDONED√ / IN USE
Present Past	: :
5. Age (Source)	
PERIOD YEARS	: 18 th Century AD :
Precise date of Construction Completion Subsequent changes Destruction / Demolition	: : :
6. Ownership / Level of Protection	on SINGLE /MULTIPLE :
Public: Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)state Govt. Private Any other (Please specify) Name Address Phone	
7. Association	
 WITH EVENTS In History In Rituals In Building Construction Any other (specify) WITH PERSONS Patron Architect / Engineer Any other (specify) Statement of Significance 	: : : :
✓ Architectural	
Archaeological Historical Religious	

	Any other (specify)	:			
			CTION II: DESCRIPTION		
9.	9. Physical Description and Decorative Features				
•	Context Urban √/ Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary)		
			Stand in Isolation Integral part of a Landscape / Street / Complex		
•	Quantification Area Dimension (L x B x H)	:			
	Number of Blocks Number of Storys	:	(m / cm/ feet / inch)		
•	Spatial Organization Orientation Plan Allocation of Spaces	: : :	The bawari is oriented East/West and faces the West.		
<u>AF</u>	CCHITECTURAL STYLE Ornamentation				
	Exteriors Interiors Movable Collections	:			
An	y Other (specify)	:			
10	. Construction Technology				

Partially dressed rubble masonry Lime, rock and marble etc.

Structural System
Building Techniques
Material of Construction

11. Condition Assessment			
In General	Good√ / Fair		
	 √ Sign of Deterioration √ Serious Deterioration Danger of Disappearance 		
In Brief (Attach extra sheet if necessary):			
The water is polluted and unfit for use. The wall is breaking carved with wild growth.			
12. Threats to the Property			
	√ Natural		
	Negligence		
	Vandalism √		
	√ V Urban Pressures		

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS