

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/BLW- 062 **SECTION I: IDENTIFICATION** 1. Name Present Hathi Gate **Past** Other Name (if any): 2. Location **LONGITUDE** 75°28'E LATITUDE 25°58'N Address Hathi Gate, Vishanoi Mohalla Ward No-2 Pur. Village (village code) Post: Pur **District:** Bhilwara State: Rajasthan **PIN**: 311802 Approach district The Gate is situated Vishanoi Mohalla Pur. It is 10km away from Bhilwara bus stand. It is well connected by regular bus services. 3. Property Type Religious structures Other Structures **Buildings** Palace Temple Wall Mosque Fort Gateway Citadel Minar Pillar Govt. building Church Others (specify) Railway station Monastery Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Engineering structure Open space and related Note: This is Pointed arched structures gateway with two pillard halls on Bridge Public square the either sides as one cross into Park or garden it. The façade of the gate is plain Tunnel pointed in white. Other engineering structure Graveyard Baolis, Well Tank

Cave

4. Property Use					
		ABANDONED / √IN USE			
Present Past	:				
5. Age (Source)					
PERIOD YEARS	:	20 th Century AD			
Precise date of Construction Completion Subsequent changes Destruction / Demolition	: : : : :				
6. Ownership / Level of Protection					
Public: Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)state Govt. Private Any other (Please specify) Name Address Phone 7. Association	: : : : : : : : : : : : : : : : : : : :	SINGLE /MULTIPLE :			
 WITH EVENTS In History In Rituals In Building Construction Any other (specify) WITH PERSONS Patron Architect / Engineer Any other (specify) 8. Statement of Significance 	: : : : : : : : : : : : : : : : : : : :				
Architectural Archaeological Historical Religious					

	Any other (specify)	:				
SECTION II: DESCRIPTION						
9.	9. Physical Description and Decorative Features					
•	Context Urban √/ Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary)			
	Ü		Stand in Isolation Integral part of a Landscape / Street / Complex			
•	Quantification Area Dimension (L x B x H)	:	(m / am/fact / inch)			
	Number of Blocks Number of Storys	:	(m / cm/ feet / inch)			
•	Spatial Organization Orientation Plan Allocation of Spaces	: : :	The gate is oriented North/South and faces the South.			
<u>AF</u>	CCHITECTURAL STYLE Ornamentation					
-	Exteriors Interiors Movable Collections	:	Name of the gate is engrened on the outer façade.			
An	y Other (specify)	:				
10. Construction Technology						

Structural System Building Techniques Material of Construction Indo Persian Arcuate

Stone, rubble masonry

11. Condition Assessment					
In General	Good√ / Fair				
	Sign of Deterioration Serious Deterioration Danger of Disappearance				
In Brief (Attach extra sheet if necessary):					
with excessive accumulation of	lack mainshrine. There is peeling and uncracking of plaster along of Pollutants in the pillard hall.				
12. Threats to the Property					
	 √ Natural Negligence √ Vandalism 				
	√ Varidalism √				

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS