

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.:RJ/BLW-119

1. Name	SECTION I: IDENTIFICATION	
Present Past Other Name (if any):	: Bansajuhar Ki Chhatri :	
2. Location		
LONGITUDE 75°28'E	LATITUDE 25°58'N	
Address	Chhatri Sanganer Gate	
	: Village (village code)	Sanganer
	Post: Sanganer State: Rajasthan	District: Bhilwara PIN: 311013
Approach district		at Sanganeri Gate in Bhilwara from Bhilwara bus stand. it is ar bus services.
3. Property Type		
Buildings	Religious structures	Other Structures
Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public building Residential building	Temple Mosque Minar	Wall Gateway Pillar Others (specify) Chhatri
Engineering structure Bridge Tunnel Other engineering structure	structures Public square Park or garden Graveyard Baolis, Well	Note: This Chhatri is placed along with other three Chhatries on a nigh rise platform. It has a domical spire and has four foliated opening arches, in each direction. The billar and the façade is plain and simple.

4. Property Use			
		ABANDONED√ / IN USE	
Present Past	:		
5. Age (Source)			
PERIOD YEARS	:	19 th Century AD	
Precise date of Construction Completion Subsequent changes Destruction / Demolition	: : :		
6. Ownership / Level of Protection			
Public: Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)state Govt. Private Any other (Please specify) Name Address Phone 7. Association	: : : : : : : : : : : : : : : : : : : :	SINGLE /MULTIPLE :	
WITH EVENTS In History In Rituals In Building Construction Any other (specify) WITH PERSONS Patron Architect / Engineer Any other (specify) Statement of Significance Architectural Archaeological	: : : : : : : : : : : : : : : : : : : :		
Historical Religious			

Any other (specify) :

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

Context

Urban √ Rural Setting Surroundings

* **Drawings** (Attach extra sheet if necessary)

Stand in Isolation

Integral part of a Landscape / Street / Complex

Quantification

Area Dimension (LxBxH):

(m / cm/ feet / inch)

01 Number of Blocks 01 Number of Storys

Spatial Organization

Orientation The chhatri is oriented East/West and faces the East.

Plan

Allocation of Spaces

ARCHITECTURAL STYLE

Ornamentation

Exteriors There are some traces of paintings undr the cornice and

along the entablature

Interiors The interior especially the interiors are painted with

bright floral patterns along the corner vicinity of the

ceilina.

Movable Collections There are cathouse masonry lime plaster.

Any Other (specify)

10. Construction Technology

Structural System Indo Persian **Building Techniques** Arcuate system

Material of Construction Stone, rubble masonry, lime plaster.

11. Condition Assessment	
In General	Good√ / Fair
	Sign of Deterioration Serious Deterioration Danger of Disappearance
In Brief (Attach extra sheet	if necessary):
	d state. The dome and the exterior well is covered with a thick layer neral pollutants. Also the plaster has peeled off and the decorative ecially the painted layer.
12. Threats to the Property	
	√ NaturalNegligenceVandalismUrban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS