

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.:RJ/BLW-185

1. Name	SECTION I: IDENTIFICATION	
Present Past Other Name (if any):	: Nath Jee Ka Well :	
2. Location		
LONGITUDE 75°28'E	LATITUDE 25°58'N	
Address	Nath Jee Ka Well Near Mu	sty Chhatri road
	: Village (village code)	Banera
	Post: Banera State: Rajasthan	District: Bhilwara PIN: 311401
Approach district		Banera in Bhilwara district. It is ilwara bus stand. it is well is services.
3. Property Type		
Buildings Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public buildings Residential building	Religious structures Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum	Other Structures Wall Gateway Pillar Others (specify)
Engineering structure Bridge Tunnel Other engineering structure	structures Public square	Note: This is a small circular stone cut wall with broken edges at the ground level, located adjacent to a temple.

4. Property Use		ADANDONED / /IN LIGE
		ABANDONED / √IN USE
Present	:	Drinking water
Past	:	
5. Age (Source)		
PERIOD	:	19 th Century AD
YEARS	:	•
Precise date of Construction	:	
Completion	:	
Subsequent changes	:	
Destruction / Demolition	:	
6. Ownership / Level of Protection	on	
		SINGLE /MULTIPLE :
Public : Archaeological Survey of	:	
India / State Archaeology		
Department / Any Other (Please		
specify)state Govt.		
Private Any other (Please specify)	:	
Name	:	
Address	•	
Phone	:	
7. Association		
WITH EVENTS		
In History		
In Rituals	:	
In Building Construction	÷	
Any other (specify)	:	
WITH PERSONS		
Patron	:	
Architect / Engineer	:	
Any other (specify)	:	
0.04-444		
8. Statement of Significance		
√ Architectural		
Archaeological		
Historical Religious		
religious		

Any other (specify)	:				
SECTION II: DESCRIPTION					
9. Physical Description and Decorative Features					
 Context Urban √ Rural Setting Surroundings 		* Drawings (Attach extra sheet if necessary)			
ourroundings		Stand in Isolation Integral part of a Landscape / Street / Complex			
Quantification Area Dimension (L x B x H)	:	(m / cm/ feet / inch)			
Number of Blocks Number of Storys	:	01 01			
 Spatial Organization Orientation Plan Allocation of Spaces 	: : :	The well is oriented East/West and faces the West.			
ARCHITECTURAL STYLE Ornamentation Exteriors Interiors Movable Collections	: : : :				
Any Other (specify)	:				
10. Construction Technology					

Structural System
Building Techniques
Material of Construction

Rubble masonry Stone

11. Condition Assessment		
In General	Good√ / Fair	
	Sign of Deterioration √ Serious Deterioration Danger of Disappearance	
In Brief (Attach extra sheet if necessary):		
The major components of the wall has broken and fallen apart. The water is extremely polluted. Also there is wild vegetational growth in around it.		
12. Threats to the Property		
	√ Natural Negligence	
	Vandalism	
	√ Urban Pressures	

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS