

## INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

## **Documentation format for Archaeological / Heritage Sites / Monuments**

Serial No.:RJ/BLW-201

1. Name	SECTION I: IDENTIFICATION	
Present Past Other Name (if any): 2. Location	: Well :	
LONGITUDE 75°28'E	LATITUDE 25°58'N	
Address	Bus stand, Badnor	
	: Village (village code)	
	Post: Badnor State: Rajasthan	District: Bhilwara PIN: 311301
Approach district	Gangapur in Bhilwara	near by Akshay Sagar at district. It is 70km away from well connected by regular bus
3. Property Type		
Buildings  Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public building Residential building	Religious structures Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum	Other Structures  Wall Gateway Pillar Others (specify) Well
Engineering structure  Bridge Tunnel Other engineering structure	structures  Public square	Note: It is a circular well cladded with rubble masonry and lime-plaster. Iron-wheels are attached to the well for fetching water.

4. Property Use		
4. Froperty Use		ABANDONED / √IN USE
Present Past	:	
5. Age (Source)		
PERIOD YEARS	:	19 <sup>th</sup> Century AD
Precise date of Construction	:	
Completion	:	
Subsequent changes	:	
Destruction / Demolition	:	
6. Ownership / Level of Protection	on_	
		SINGLE /MULTIPLE :
<b>Public</b> : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)state Govt.	:	
Private	:	
Any other (Please specify)	:	
Name	:	
Address	:	
Phone	:	
7. Association		
WITH EVENTS		
In History	:	
In Rituals	:	
In Building Construction	:	
Any other (specify)	:	
WITH PERSONS		
Patron	:	
Architect / Engineer Any other (specify)	•	
Any other (specify)	•	
8. Statement of Significance		
<ul><li>√ Architectural</li><li>Archaeological</li><li>Historical</li></ul>		

	Religious Any other (specify)	:			
SECTION II: DESCRIPTION  9. Physical Description and Decorative Features					
Context     Urban √/ Rural Setting     Surroundings		* <b>Drawings</b> (Attach extra sheet if necessary)			
	<b>J</b>		Stand in Isolation Integral part of a Landscape / Street / Complex		
•	<b>Quantification</b> Area Dimension ( L x B x H)	:	(m / cm/ feet / inch)		
	Number of Blocks Number of Storys	:	(III / GITW TOOK / III GIT)		
•	Spatial Organization Orientation Plan Allocation of Spaces	: : :	The well is oriented East/West and faces the East.		
<u>AR</u>	Ornamentation Exteriors Interiors	:	Well cladded with rubble masonry		
	Movable Collections by Other (specify)  Construction Technology	:			

Step well

Structural System
Building Techniques
Material of Construction Rubble masonry and plaster.

11. Condition Assessment	
In General	Good√ / Fair
	Sign of Deterioration Serious Deterioration Danger of Disappearance
In Brief (Attach extra sheet	t if necessary):
Pilling of plaster etc.	
12. Threats to the Property	ı en
	<ul><li>√ Natural</li><li>Negligence</li><li>Vandalism</li><li>Urban Pressures</li></ul>

## **SECTION III:** REFERENCES

## 13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS