

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/BLW-273 **SECTION I: IDENTIFICATION** 1. Name Present Well Past Other Name (if any): 2. Location **LONGITUDE** 75° 28' E LATITUDE 25°58' N Bus stand Mandal **Address** : Village (village code) Mandal Post: Mandal **District:** Bhilwara **State**: Rajasthan **PIN:** 311401 Approach The Well is situated Dhomani Talab Pal Mandal. It is 14 Km from Bhilwara. It is well connected by regular bus services. 3. Property Type Religious structures Other Structures **Buildings** Palace Temple Wall Fort Mosque Gateway Citadel Minar Pillar Govt. building Church Others (specify) Railway station Monastery Defence building Stupa Tomb, Mausoleum Industrial building Other public buildings Residential building Open space and related the well is enclosed Engineering structure Note: structures in a concrete complex. It is a shallow well not very deep. Bridge Public square It includes a small sheltered Tunnel Park or garden

Other engineering structure	Graveyard Baolis, Well Tank Cave	structure. The well stands alongside the road. It is in domestic usage. The well has bush green trees and					
4.11oporty 000	APANDONED	/ IN					
	ABANDONED USE √ :	/ IN					
Present Past	: :						
5. Age (Source)							
PERIOD YEARS	: 19 th Century AD						
Precise date of Construction	:						
Completion Subsequent changes	:						
Destruction / Demolition	:						
6. Ownership / Level of Protection							
SINGLE /MULTIPLE :							
Public: Archaeological Survey of India / State Archaeology Department / Any Other	:						
(Please specify) Private	:						
Any other (Please specify) Name	:						
Address	:						
Phone	:						
7. Association							
WITH EVENTS							
√ In History	:						
In Rituals In Building Construction	:						
in banding constitution	•						

: : : : : : : : : : : : : : : : : : : :		
:		ficance
<u>ION II:</u> DESCRI tion and	PTION Decorative	Features
Urban setting Stand in Isol	ation of a Landscape / S	•,
The Well is o	oriented east/west a	nd faces the west
No ornamenta	ation	
	: ION II: DESCRII tion and * Drawings (Urban setting Stand in Isol Integral part The Well is of	* Drawings (Attach extra sheet if Urban setting Stand in Isolation Integral part of a Landscape / S The Well is oriented east/west a

Structural System Building Techniques Material		- Rubble masonry and stone cladding Stone, concrete
Construction		
,		
11. Condition Assessmen	ıt	
In General	Good	d / Fair Good
		Sign of Deterioration Serious Deterioration Danger of Disappearance
In Brief (Attach extra shee	et if ne	ecessary):
The well is not in very good	condi	tion but also used by domestic purpose
12. Threats to the Propert	y	
		Natural
		Negligence
	-	Vandalism
		l Urhan Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	ach list as in page 6, in case of multiple photographs)
	aon not do in pago o, in odos or manipio priotographo,
Photo Reference	
CAPTION	
-	
15. Audio / Video	
10. Addio / Video	(related to rituals / performance / festivals
	(related to rituals / performance / restivals
etc.)	
•	
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
4-1-4	
17. Listers	
NAME	NAME
18. Reviewers	
10.17641644613	
NAME	NAME
	NAME
	NAME COMMENTS

Details of Each Image

S. No.	Image file Name	Caption/Description	Remarks
1		Wide view	
2		Corner	
3		Close view	
4		Deep	
5		Close view	
6		Side view	
7		Font view	
8		Deep	
9		Deep	
10		Corner	
11		Corner	
12		Corner	