

1. Name

Present

2. Location

Address

Palace

Citadel

Bridge

Tunnel

Other engineering structure

Fort

**Past** 

#### INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

#### **Documentation format for Archaeological / Heritage Sites / Monuments**

Serial No.:RJ/BLW-439 **SECTION I: IDENTIFICATION** Palacial Building Other Name (if any): **LONGITUDE** 75°28'E LATITUDE 25°58'N Kila Mandalgarh Village (village code) Post: Mandalgarh **District:** Bhilwara State: Rajasthan **PIN**: 311605 Approach district The Khandar is situated at Kila Mandalgarh in Bhilwara district. It is 55km away from Bhilwara bus stand. it is well connected by regular bus services. 3. Property Type Religious structures Other Structures **Buildings** Temple Wall Mosque Gateway Minar Pillar Others (specify) Govt. building Church Railway station Monastery khandar Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Engineering structure Open space and related **Note:** It is dilapidated structure. structures The structure has pointed arch Public square opening. Damaged walls and

pillars can be seen all over the

place.

Park or garden Graveyard

Baolis, Well Tank Cave

4. Property Use	
	ABANDONED√ / IN USE
Present Past	: :
5. Age (Source)	
PERIOD YEARS	: 17 <sup>th</sup> Century AD
Precise date of Construction Completion Subsequent changes Destruction / Demolition	: : :
6. Ownership / Level of Protection	
Public: Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)state Govt. Private Any other (Please specify) Name Address Phone 7. Association	SINGLE /MULTIPLE : : : : : : : : : : : : : : : : : : :
WITH EVENTS     In History     In Rituals     In Building Construction     Any other (specify)      WITH PERSONS     Patron     Architect / Engineer     Any other (specify)  8. Statement of Significance	: : : :
Archaeological Historical Religious	

	Any other (specify)	:	
	<u> </u>	SEC	CTION II: DESCRIPTION
9.	Physical Description and De-	cor	ative Features
•	Context Urban √ Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary)
			Stand in Isolation Integral part of a Landscape / Street / Complex
•	<b>Quantification</b> Area Dimension ( L x B x H)	:	(m / cm/ feet / inch)
	Number of Blocks Number of Storys	:	01 01
•	Spatial Organization Orientation Plan Allocation of Spaces	: : : :	The Khandar is oriented East/West and faces the West.
•	Ornamentation Exteriors Interiors Movable Collections ny Other (specify)	: : : : : : : : : : : : : : : : : : : :	Pointed arch opening.

# 10. Construction Technology

Structural System Building Techniques Material of Construction Indo Persian Arcuate system Stone

11. Condition Assessment					
In General	Good /√ Fair				
	Sign of Deterioration Serious Deterioration Danger of Disappearance				
In Brief (Attach extra sheet if necessary):					
Badly damaged					
12. Threats to the Property					
	<ul><li>√ Natural</li><li>Negligence</li><li>Vandalism</li><li>Urban Pressures</li></ul>				

# **SECTION III:** REFERENCES

### 13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS

### **Details of Each Image**

S. No.	Image file Name	Caption/Description	Remarks
1		Wide view	
2		Wide view	
3		Side view	
4		Side view	
5		Front view	
6		Front view	
7		Front view	
8		Close view	
9		Close view	
10		Side view	
11		Side view	
12		Side view	
13			
14			
15			
16			
17			