

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

<u> </u>	,	30.90			
Documentation format for Archaeological / Heritage Sites / Monuments					
1. Name	SECTION I: IDENTIFICATION	Serial No.: RJ/BLW-516			
Present Past Other Name (if any): 2. Location	: Narsingh Bhagwan Man : :	dir			
LONGITUDE 75°28'E	LATITUDE 25°58'N				
Address	Near Nilkanth Mahadev Mar	ndir Ward Nor-4			
	: Village (village code)	Pur			
	Post: Pur State: Rajasthan	District: Bhilwara PIN: 311802			
Approach district	Pur in Bhilwara district.	at Nilkanth Mahadev Mandir It is 10km away from Bhilwara e connected by regular bus			
3. Property Type					
Buildings Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public building Residential building	Religious structures Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum	Other Structures Wall Gateway Pillar Others (specify)			
Engineering structure Bridge Tunnel Other engineering structure	<u>structures</u>	Note: . It is a beautiful temple dedicated to lord Narsingh Bhagwan.			

4. Property Use		
		ABANDONED / √IN USE
Present Past	:	Religious Religious
5. Age (Source)		
PERIOD YEARS	:	18 th Century AD
Precise date of Construction Completion Subsequent changes Destruction / Demolition	: :	
6. Ownership / Level of Protection	<u>on</u>	
		SINGLE /MULTIPLE :
Public: Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)state Govt. Private Any other (Please specify) Name Address Phone	: : : : : : : : : : : : : : : : : : : :	
7. Association		
 WITH EVENTS In History In Rituals In Building Construction Any other (specify) WITH PERSONS Patron Architect / Engineer Any other (specify) 	: : : : : : : : : : : : : : : : : : : :	Temple.
8. Statement of Significance		
Architectural Archaeological Historical Religious Any other (specify)	:	

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features					
•	Context * Urban √/ Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary)		
	J		Stand in Isolation Integral part of a Landscape / Street / Complex		
•	Quantification Area Dimension (L x B x H)	:	(m / cm/ feet / inch)		
	Number of Blocks Number of Storys	:	(III7 GIII/ IGGE7 IIIGII)		
•	Spatial Organization Orientation	:	The Temple is Oriented North/South and faces the South.		
	Plan Allocation of Spaces	:	South.		
•	Ornamentation Exteriors Interiors Movable Collections y Other (specify)	: : : : : : : : : : : : : : : : : : : :			
10.	Construction Technology				
	Structural System Building Techniques Material of Construction	: : :	Square Temple Stone, Plaster		
11.	Condition Assessment				
	In General G	ood∖	/ Fair		
			Sign of Deterioration Serious Deterioration Danger of Disappearance		

In Brief (Attach extra sheet if necessary):

The exterior wall is peeling off due to mainshrine and varied temperature. Also there is Staiwind discoloration of the stone layed for flooring.

12. Threats to the Prope

√ Natural
 √ Negligence
 √ Vandalism
 √ Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CARTION	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
111 2101010	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS