

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/BMR-016 **SECTION I: IDENTIFICATION** 1. Name Present Shiv Mandir Past Other Name (if any): Tat Kaleswar Mahadev Mandir 2. Location LONGITUDE 72⁰ 52[']F LATITUDE 26⁰ 31'N **Address** Keradu, Barmer Village (village code) Keradu Post: Hatama District: Barmer State: Rajasthan PIN: 344001 **Approach** The temple is situated at Keradu in Barmer. It is 33 Km away from Barmer district. It is well connected by regular bus service 3. Property Type Buildings Religious structures Other Structures Palace Temple Wall Mosque Fort Gateway Citadel Minar Pillar Govt. building Church Others (specify) Railway station Monastery Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential buildings Engineering structure Open space and related Note: It is an old temple built in structures Nagara style. It has curvilinear Shikhara with Augshikhara. It has Bridge Public square a huge Aamalka and missing Park or garden Tunnel pinnacle. There are intricate Other engineering structure Graveyard carvings on the outer surface as Baolis, Well well as doorjamb. Te mutilated Tank part and broken part are scattered Cave all around.

4. Property Use ABANDONED / IN USE: Abandoned Present **Past** Religious 5. Age (Source) PERIOD 13th Century AD YEARS **Precise date of Construction** Completion Subsequent changes **Destruction / Demolition** 6. Ownership / Level of Protection SINGLE /MULTIPLE: **Public**: Archaeological Survey of : State Archaeological Department India/ State Archaeological Department/ / Any Other (Please specify) **Private** Any other (Please specify) Name Address Phone 7. Association WITH EVENTS In History In Rituals In Building Construction Any other (specify) WITH PERSONS **Patron** Architect / Engineer □ Any other (specify) 8. Statement of Significance Architectural Archaeological Historical Religious Any other (specify)

		SEC	CTION II: DESCRIPTION			
9 . l	9. Physical Description and Decorative Features					
•	Context Urban / Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary) Urban			
			Stand in Isolation Integral part of a Landscape / Street / Complex			
•	Quantification Area Dimension (L x B x H	· i	(no / one/foot (in sh)			
	Number of Blocks Number of Storys	:	(m / cm/ feet / inch) 01			
•	Spatial Organization Orientation	:	The temple is oriented East/West and faces the East.			
	Plan Allocation of Spaces	:				
<u>AR</u>	CHITECTURAL STYLE Ornamentation Exteriors Interiors	:	Curvilinear Shikhara with Aamaka and augshikhara. Carving all over.			
10.	Movable Collections Any Other (specify) Construction Technology	: : /				
	Structural System Building Techniques Material of Construction	: :	Trabeate system. Nagara Style Stones.			
11.	Condition Assessment					
		Good A	/ Fair			
./	Olama at Da atawia wation					

Sign of Dseterioration
Serious Deterioration
Danger of Disappearance

In Brief (Attach extra sheet if necessary): Semi ruined state

12. Threats to the Property

✓	Natural
✓	Negligence
	Vandalism
	Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)				
References.				
44 Dhetegraphs				
14. Photographs	(attach list as in page 6, in case of multiple photographs)			
Photo Reference	(andor not do in page of in each of maniple priotographie)			
Photo Reference				
CAPTION				
15. Audio / Video	(related to rituals / norfermance / feetivels etc.)			
	(related to rituals / performance / festivals etc.)			
Reference				
DESCRIPTION				
16. Maps/Plans/Drawings				
17. Listers				
NAME	NAME			
NAME	NAME			
18. Reviewers				
NAME	NAME			
COMMENTS	COMMENTS			