

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/BMR-018 **SECTION I: IDENTIFICATION** 1. Name Present Statue Past Other Name (if any): 2. Location LONGITUDE 72⁰ 56[']F LATITUDE 26⁰ 31'N **Address** Keradu, Barmer Village (village code) Keradu Post: Hatama District: Barmer State: Rajasthan PIN: 344001 Approach The Statue is situated near Keradu mandir in Barmer. It is 33 Km away from Barmer district. It is well connected by regular bus service 3. Property Type **Buildings** Religious structures **Other Structures** Palace Temple Wall Mosque Fort Gateway Citadel Minar Pillar Govt. building Church Others (specify) Railway station Monastery Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Engineering structure Open space and related **Note:** This is a ruin of a temple. There are different fragmented structures part the temple scattered all Bridge Public square around. We can see the Amalaka, Tunnel Park or garden Graveyard Pillars, Bharvahak Gondhava Other engineering structure celestial beings, sculpted panels Baolis, Well amorous couple, and so on. Tank Cave

4. Property Use ABANDONED / IN USE: Abandoned Present **Past** Religious 5. Age (Source) PERIOD 13th Century AD YEARS **Precise date of Construction** Completion Subsequent changes **Destruction / Demolition** 6. Ownership / Level of Protection SINGLE /MULTIPLE: **Public**: Archaeological Survey of : State Archaeological Department India / State Archaeology Department / Any Other (Please specify) **Private** Any other (Please specify) Name Address Phone 7. Association WITH EVENTS In History In Rituals In Building Construction Any other (specify) WITH PERSONS **Patron Architect / Engineer** Any other (specify) 8. Statement of Significance Architectural Archaeological Historical Religious Any other (specify)

SECTION II: DESCRIPTION

9.	Physical Description and I	Decora	itive reatures			
•	Context Urban / Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary) Urban			
	Carroanange		Stand in Isolation Integral part of a Landscape / Street / Complex			
•	Quantification Area Dimension (L x B x F	H) :	(m / am/fact / inch)			
	Number of Blocks Number of Storys	: :	(m / cm/ feet / inch)			
•	Spatial Organization Orientation	:	The statue is oriented East/West and faces the East.			
	Plan Allocation of Spaces	:				
ARCHITECTURAL STYLE • Ornamentation						
	Exteriors	:	Ruins of a temple.			
10	Interiors Movable Collections Any Other (specify) Construction Technology	: : :				
11.	Structural System Building Techniques Material of Construction Condition Assessment	:	Stone.			
	In General	Good	/ Fair			
√	Sign of Deterioration Serious Deterioration Danger of Disappearance	Fair				
	Brief (Attach extra sheet if	fneces	ssary):			
Dil	Dilapidated					

12.	Threats	to the	Pro	perty
-----	----------------	--------	-----	-------

✓ Natural
✓ Negligence
✓ Vandalism
Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS