



INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/BMR-071

SECTION I : IDENTIFICATION

1. Name

Present : Veer Durgadas Pol
 Past :
 Other Name (if any): :

2. Location

LONGITUDE 72° 52'E **LATITUDE** 26° 31'N

Address

Haldeshavar Mahadev Mandir, Piplun, Siwana

: **Village (village code)** Piplun
Post : Siwana **District:** Barmer
State : Rajasthan **PIN: 344044**

Approach

: The Gateway is situated at Piplun in Barmer. It is 140 Km away from Barmer district. It is well connected by regular bus service

3. Property Type

Buildings

- Palace
- Fort
- Citadel
- Govt. building
- Railway station
- Defence building
- Industrial building
- Other public buildings
- Residential building

Religious structures

- Temple
- Mosque
- Minar
- Church
- Monastery
- Stupa
- Tomb, Mausoleum
-
-

Other Structures

- Wall
- Gateway
- Pillar
- Others (specify)
- _____
- _____
- _____
- _____

Engineering structure

- Bridge
- Tunnel
- Other engineering structure

Open space and related structures

- Public square
- Park or garden
- Graveyard
- Baolis, Well
- Tank
- Cave

Note: This is a large gateway stand on a hill top. It is adjoin with huge bastion and fortification wall. It has pointed arch opening. It has congura pattern battlemented design.

4. Property Use

ABANDONED / IN USE : In Use

Present :
Past :

5. Age (Source)

PERIOD : 17th Century AD
YEARS :
Precise date of Construction :
Completion :
Subsequent changes :
Destruction / Demolition :

6. Ownership / Level of Protection

SINGLE /MULTIPLE :

Public : Archaeological Survey / :
India/ State Archaeological
Department/
Any Other (Please specify)

Private :
Any other (Please specify) :
Name :
Address :
Phone :

7. Association

- **WITH EVENTS**
 - In History** :
 - In Rituals** :
 - In Building Construction** :
 - Any other (specify)** :
- **WITH PERSONS**
 - Patron** :
 - Architect / Engineer** :
 - Any other (specify)** :

8. Statement of Significance

- Architectural
- Archaeological
- Historical
- Religious
- Any other (specify)

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

- **Context** : * **Drawings** (Attach extra sheet if necessary)

Urban / Rural Setting : Rural
Surroundings : **Stand in Isolation**
Integral part of a Landscape / Street / Complex

- **Quantification**
Area Dimension (L x B x H) : (m / cm/ feet / inch)

Number of Blocks : 01
Number of Storys : 01

- **Spatial Organization**
Orientation : The Gateway is oriented East /West and faces the East

Plan :
Allocation of Spaces :

ARCHITECTURAL STYLE

- **Ornamentation**
Exteriors : Pointed arch openings, Congura pattern battlement

Interiors :
Movable Collections :

Any Other (specify) :

10. Construction Technology

- Structural System** : Indo Persian
- Building Techniques** : Arcuate
- Material of Construction** : Stone and Lime masonry

11. Condition Assessment

In General : **Good / Fair**
Good

- | | |
|---|-------------------------|
| ✓ | Sign of Deterioration |
| ✓ | Serious Deterioration |
| | Danger of Disappearance |

In Brief (Attach extra sheet if necessary):

Semi ruined state

12. Threats to the Property

- | | |
|-------------------------------------|-----------------|
| <input checked="" type="checkbox"/> | Natural |
| <input checked="" type="checkbox"/> | Negligence |
| <input checked="" type="checkbox"/> | Vandalism |
| <input type="checkbox"/> | Urban Pressures |

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

Reference

14. Photographs

(attach list as in page 6, in case of multiple photographs)

Photo Reference

CAPTION

15. Audio / Video

(related to rituals / performance / festivals etc.)

Reference

DESCRIPTION

16. Maps/Plans/Drawings

17. Listers

NAME

NAME

18. Reviewers

NAME

NAME

COMMENTS

COMMENTS