

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/BMR-073

1. Name	SECTION I : IDENTIFICATION	N
Present Past Other Name (if any): 2. Location	: Ganga Kund : :	
LO	NGITUDE 72º 52 [°] E LATI	TUDE 26 ⁰ 31'N
Address	Haldeshavar Mahadev Ma	ndir, Piplun, Siwana
	: Village (village code) Post : Siwana State : Rajasthan	Piplun District: Barmer PIN: 344044
Approach 3. Property Type		at Piplun in Barmer. It is 140 Km istrict. It is well connected by
Buildings	Religious structures	Other Structures
 Palace Fort Citadel Govt. building Defence building Industrial building Other public buildings Residential building 	Temple Mosque Minar Church Stupa Tomb, Mausoleum	Wall Gateway Pillar ✓ Others (specify)
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structuresPublic squarePark or gardenGraveyardBaolis, WellTankCave	Note: It is a sacred pond situated near the Mahadev Mandir. It's water is used for ritualistic purpose. The water is also used to cure the skin disease.

4. Property Use

ABANDONED / IN USE : In Use

Present	: Religious
Past	: Religious
5. Age (Source)	

5. Age (Source)	
PERIOD	: 17 th Century AD
YEARS	:
Precise date of Construction	:
Completion	:
Subsequent changes	:
Destruction / Demolition	:

6. Ownership / Level of Protection

SINGLE /MULTIPLE :

Public : Archaeological Survey /India/StateArchaeologicalDepartment/Any Other (Please specify)PrivateAny other (Please specify)NameAddressPhone	
7. Association	
 WITH EVENTS In History In Rituals In Building Construction	: : : :
 Architectural Archaeological Historical Religious Any other (specify) 	

SECTION II: DESCRIPTION

9.	Physical Description and I	Decora	ative Features
•	Context		* Drawings (Attach extra sheet if necessary)
	Urban / Rural Setting Surroundings		Rural
			Stand in Isolation Integral part of a Landscape / Street / Complex
•	Quantification Area Dimension(L x B x H	ł) :	
	Number of Blocks	:	(m / cm/ feet / inch) 01
	Number of Storys	:	01
•	Spatial Organization Orientation Plan Allocation of Spaces	:	The Kund is oriented North/South and faces the South
<u>A</u> F	RCHITECTURAL STYLE		
•	Ornamentation Exteriors Interiors	:	Renovation work done in recent past
	Movable Collections	:	
	Any Other (specify)	:	
10	. Construction Technology	/	
	Structural System	:	Kund
	Building Techniques	:	
	Material of Construction	:	Stone, Plaster
11	. Condition Assessment		
		Good Good	/ Fair
✓ 	Sign of Deterioration Serious Deterioration Danger of Disappearance		
In	Brief (Attach extra sheet if	nece	ssary):
Pc	olluted water		

12. Threats to the Property

✓	Natural
~	Negligence
	Vandalism
	Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME