

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/BRN-45 **SECTION I: IDENTIFICATION** 1. Name **Present** Char Khamba Mandir Past Other Name (if any): 2. Location 25° 26' N LONGITUDE 77° 26' E LATITUDE **Address** Vilas Garh, Baran Village (village code) Post: Baran District: Baran State: Rajasthan PIN: 325205 Approach The Mandir is situated at Bajrang Garh in Baron District. It is 35 km from Baran bus stand. It is well connected by regular bus services. 3. Property Type **Buildings** Religious structures Other Structures Temple Wall Palace Fort Mosque Gateway Citadel Minar Pillar Govt. building Church Others (specify) Railway station Monastery Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Engineering structure Open space and related Note: The structure is an ancient structures one. It has four broad pillars and Public square is devoid roof. Bridge Tunnel Park or garden Graveyard Other engineering structure Baolis, Well Tank

Cave

4. Property Use	
	ABANDONED / IN USE: In use
Present Past	: Religious : Religious
Fast	: Religious
5. Age (Source)	
PERIOD	: 8 th Century A.D.
YEARS	:
Precise date of Construction	:
Completion	:
Subsequent changes	:
Destruction / Demolition	:
6. Ownership / Level of Protecti	ion
	SINGLE /MULTIPLE :
India / State Archaeology	:
Department / Any Other (Please specify)	
Private	:
Any other (Please specify)	:
Name	:
Address	:
Phone	:
7. Association	
WITH EVENTS	
In History	: Temple
In Rituals	:
In Building Construction	:
Any other (specify)	:
 WITH PERSONS 	
Patron	:
Architect / Engineer	:
Any other (specify)	:
8. Statement of Significance	
✓ Architectural	Pillars
Archaeological	
Historical Religious	
Any other (specify)	

SECTION II: DESCRIPTION

9. P	hysical Description and	Decora	ative Features
Context Urban / Rural Setting Surroundings			* Drawings (Attach extra sheet if necessary) Urban
	ourroundings		Stand in Isolation Integral part of a Landscape / Street / Complex
	Quantification Area Dimension(L x B x H	H) :	(m / am/fact / inch)
	Number of Blocks Number of Storys	:	(m / cm/ feet / inch) 01 01
	Spatial Organization Orientation Plan Allocation of Spaces	: : :	The Temple is oriented East/West and faces the East
•	CHITECTURAL STYLE Ornamentation Exteriors Interiors Movable Collections Other (specify)	: : :	Pillars
10.	Construction Technology	у	
	Structural System Building Techniques Material of Construction Condition Assessment	: :	Indo-Persian Arcuate Sandstone
	In General	Good	/ Fair
In B	Sign of Deterioration Serious Deterioration Danger of Disappearance Brief (Attach extra sheet in		ssary):
Blad	ckening of surface		

12. Threats to the Property	
	Natural Negligence Vandalism Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS