

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/BRN-53

	SECTION I : IDENTIFICATION
1. Name	
Present Past Other Name (if any):	: Jain Mandir-7 :
2. Location	
LONGITUDE 77 ⁰ 26 [°] E	LATITUDE 25 ⁰ 26 [°] N
Address	Bilas Garh, Baran
Approach	 : Village (village code) Post : Bajrang Garh State : Rajasthan : The Mandir is situated at Bilaspur Garh in Baron District. It is 35 km from Baran bus stand. It is well connected by regular bus services.
3. Property Type	
Buildings	Religious structures Other Structures
Palace	✓ Temple Wall
Fort	Mosque Gateway
Citadel	Minar Pillar
Govt. building Railway station	Church Others (specify) Monastery
Defence building	Stupa
Industrial building	Tomb, Mausoleum
Other public buildings	
Residential building	

Engineering structure

Engineering structure	Open space and related structures		Note: The wall of temple is richly carved with various designs. It is	
Bridge		Public square	de	evoid of roof.
Tunnel		Park or garden		
Other engineering structure		Graveyard		
		Baolis, Well		
		Tank		
		Cave		

4. Property Use

	ABANDONED / IN USE : Abandoned
Present	:
Past	: Religious
5. Age (Source)	
PERIOD	: 08 th Century A.D.
YEARS	:
Precise date of Construction	:
Completion	:
Subsequent changes	:
Destruction / Demolition	:
6. Ownership / Level of Protection	on
	SINGLE /MULTIPLE :
Public : Archaeological Survey of	:
India / State Archaeology	
Department / Any Other (Please	
specify)	
Private	:
Any other (Please specify)	:
Name	:
Address	:
Phone	:
7. Association	
WITH EVENTS	
In History	: Temple
In Rituals	:
In Building Construction	:
Any other (specify)	:
WITH PERSONS	
Patron	:
Architect / Engineer	
Any other (specify)	:
8. Statement of Significance	
✓ Architectural	
✓ Archaeological	Ruins of Jain temples
Historical	
Religious	
Any other (specify)	

SECTION II: DESCRIPTION

9.	9. Physical Description and Decorative Features		
•	Context Urban / Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary) Urban
	Curroundings		Stand in Isolation Integral part of a Landscape / Street / Complex
•	Quantification Area Dimension (L x B x H)	:	(m / cm/ feet / inch)
	Number of Blocks Number of Storys	:	02 03
•	Spatial Organization Orientation Plan Allocation of Spaces	:	The Temple is oriented East/West and faces the West
•	RCHITECTURAL STYLE Ornamentation Exteriors Interiors Movable Collections ny Other (specify)	:	Richly carved walls

10. Construction Technology

Structural System Building Techniques Material of Construction	:	Indo-Persian Arcuate Sandstone
Material of Construction	:	Sandstone

11. Condition Assessment

In General	Good / Fair	
	Good	

Sign of Deterioration Serious Deterioration Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Blackening of surface.

12. Threats to the Property

Natural Negligence Vandalism Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS