

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/BRN-68 **SECTION I: IDENTIFICATION** 1. Name Present Shre Vishnu jee Mandir Past Other Name (if any): 2. Location **LONGITUDE** 76° 26' E 25⁰ 51['] N LATITUDE **Address** Bilas Garh, Baran Village (village code) Post: Bajrang Garh District: Baran State: Rajasthan PIN: 325216 **Approach** The temple is situated at Bilas Garh in Baron District. It is 35 km from Baran bus stand. It is well connected by regular bus services. 3. Property Type **Buildings** Religious structures Other Structures Temple Wall Palace Fort Mosque Gateway Citadel Minar Pillar Govt. building Church Others (specify) Railway station Monastery Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Engineering structure Open space and related Note: The temple has image of structures Ganesha on the lalat bimb of door Public square lantel. The pillars are broad and Bridge richly carved and supporting the Tunnel Park or garden structure. The temple is devoid of Graveyard Other engineering structure roof. Baolis, Well Tank

Cave

4. Property Use	
	ABANDONED / IN USE: Abandoned
Present Past	: Religious
5. Age (Source)	
PERIOD YEARS Precise date of Construction Completion Subsequent changes Destruction / Demolition 6. Ownership / Level of Protection	: 06 th Century A.D. : : : : :
	SINGLE /MULTIPLE :
Public: Archaeological Survey of India / State Archaeology Department / Any Other (Please specify) Private Any other (Please specify) Name Address Phone	: : : : :
7. Association	
 WITH EVENTS In History In Rituals In Building Construction Any other (specify) WITH PERSONS Patron Architect / Engineer Any other (specify) 	: Temple : : : :
8. Statement of Significance	
✓ Architectural Archaeological Historical Religious Any other (specify)	Broad pillars with richly carved designs.

SECTION II: DESCRIPTION

9.	Physical Description and I	Decora	ative Features	
•	Context Urban / Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary) Urban	
	Carroanange		Stand in Isolation Integral part of a Landscape / Street / Complex	
•	Quantification Area Dimension (L x B x F	· d) :	(m / cm/ feet / inch)	
	Number of Blocks Number of Storys	:	02 03	
•	Spatial Organization Orientation Plan Allocation of Spaces	: : :	The Temple is oriented North/South and faces the South	
•	CHITECTURAL STYLE Ornamentation Exteriors Interiors Movable Collections y Other (specify)	: : :	Ganesha image on lalat bimb	
10. Construction Technology				
11	Structural System Building Techniques Material of Construction Condition Assessment	: : :	Indo – Persian Arcuate Sandstone	
	In General	Good	/ Fair	
	50110141	Good	, - 	
	Sign of Deterioration Serious Deterioration Danger of Disappearance	;		
In	Brief (Attach extra sheet it	nece	ssary):	
Bla	ackening of surface.			

12. Threats to the Property	
	Natural Negligence Vandalism Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CARTION	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS
LALIMINICIALIA	CACIVITIES 1.3