

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/BRN-70 **SECTION I: IDENTIFICATION** 1. Name Present Vishnu Mandir Past Other Name (if any): 2. Location 25° 26' N LONGITUDE 77° 26' E LATITUDE **Address** Bilas Garh, Baran Village (village code) Post: Bajrang Garh District: Baran State: Rajasthan PIN: 325216 **Approach** The temple is situated at Bilas Garh in Baron District. It is 35 km from Baran bus stand. It is well connected by regular bus services. 3. Property Type **Buildings** Religious structures Other Structures Palace Temple Wall Fort Mosque Gateway Citadel Minar Pillar Govt. building Church Others (specify) Railway station Monastery Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Engineering structure Open space and related Note: Temple has decorative structures pillars and flat roof surface. The Public square architecture remains Bridge are scattered all around. Tunnel Park or garden Graveyard Other engineering structure Baolis, Well Tank

Cave

4. Property Use	
	ABANDONED / IN USE: Abandoned
Present Past	: Religious
5. Age (Source)	
PERIOD YEARS Precise date of Construction Completion Subsequent changes Destruction / Demolition 6. Ownership / Level of Protection	: 09 th Century A.D. : : :
o. Ownership? Level of Froteon	SINGLE /MULTIPLE :
Public: Archaeological Survey of India / State Archaeology Department / Any Other (Please specify) Private Any other (Please specify) Name Address Phone	
WITH EVENTS In History In Rituals In Building Construction Any other (specify) WITH PERSONS Patron Architect / Engineer Any other (specify) 8. Statement of Significance	: Temple : : :
Architectural ✓ Archaeological Historical Religious Any other (specify)	Ruins of Vishnu temple

SECTION II: DESCRIPTION

9.	Physical Description and I	Decora	ative Features
Context Urban / Rural Setting Surroundings			* Drawings (Attach extra sheet if necessary) Urban
	Carroananigo		Stand in Isolation Integral part of a Landscape / Street / Complex
•	Quantification Area Dimension (L x B x F	Н) :	(m / am/fact / inch)
	Number of Blocks Number of Storys	:	(m / cm/ feet / inch) 01 01
•	Spatial Organization Orientation Plan Allocation of Spaces	: : :	The Temple is oriented North/South and faces the North
•	Ornamentation Exteriors Interiors Movable Collections y Other (specify)	: : :	Pillars
10	Construction Technology	y	
11	Structural System Building Techniques Material of Construction Condition Assessment		Indo – Persian Arcuate Sandstone
		Good	/ Fair
		Good	
	Sign of Deterioration Serious Deterioration Danger of Disappearance)	
In	Brief (Attach extra sheet if	fneces	ssary):
Bla	ckening of surface.		

12. Threats to the Property	
	Natural Negligence Vandalism Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
o/ 1101.	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
WAINE	White
18. Reviewers	
NAME	NAME
0044451470	0011151170
COMMENTS	COMMENTS