

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS


Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/DLP-014

1. Name	SECTION I : IDENTIFICATION
Present Past Other Name (if any):	: Kalyan Singh ki Chhatri
2. Location	
LONGITUDE 78° 17 ['] E	LATITUDE 27 ⁰ 50 ['] N
Address	Shergarh Fort, Dhaulpur
	: Village (village code) Post : Dhaulpur District: Dhaulpur State : Rajasthan PIN: 328001
Approach	 The Temple is situated at Shergarh fort in Dhaulpur. It is 4 Km away from Dhaulpur bus stand. It is well connected by regular bus service.

3. Property Type



4. Property Use ABANDONED / IN USE : Abandoned Present Memorial 2 Memorial Past • 5. Age (Source) 19th Century AD PERIOD 2 YEARS 2 Precise date of Construction 2 Completion : Subsequent changes : **Destruction / Demolition** : 6. Ownership / Level of Protection SINGLE /MULTIPLE : **Public** : Archaeological Survey of : India / State Archaeology Department / Any Other (Please specify) Private 2 Any other (Please specify) : Name 2 Address 2 Phone ÷ 7. Association WITH EVENTS In History : In Rituals : In Building Construction : Any other (specify) Memorial : WITH PERSONS Patron : **Architect / Engineer** : Any other (specify) : 8. Statement of Significance Architectural Archaeological Historical Religious

Any other (specify)

Domical Superstructure

SECTION II: DESCRI

9. Physical Description and Decorative Features					
•	Context Urban / Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary) Urban Stand in Isolation Integral part of a Landscape / Street / Complex		
•	Quantification Area Dimension (L x B x H) Number of Blocks Number of Storys	:	(m / cm/ feet / inch) 01 01		
•	Spatial Organization Orientation Plan Allocation of Spaces	:	The Chhatri is oriented East/West and faces the East.		
•	RCHITECTURAL STYLE Ornamentation Exteriors Interiors Movable Collections by Other (specify)		Canopied chhatri, foliated arch, Medallion		

10. Construction Technology

Structural System Building Techniques	Indo Persian Arcuate system
Material of Construction	Stone and Plaster

11. Condition Assessment

In General

Good / Fair Good

Sign of Deterioration Serious Deterioration Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Blackening of Surface, Plaster peeling off.

12. Threats to the Property

Natural Negligence Vandalism Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS