

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS


Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/DLP-062

1. Name	SECTION I : IDENTIFICATION	
Present Past Other Name (if any):	: Bihari Das ki Chhatri :	
2. Location		
LONGITUDE 78° 17' E	LATITUDE 27 ⁰ 50 [°] N	
Address	Machkund, Dhaulpur	
	: Village (village code) Post : Dhaulpur District: Dhaulpur State : Rajasthan PIN: 328001	
Approach	 The Chhatri is situated at Machkund in Dhaulpur. It is 4 k.m. away from Dhaulpur city bus stand. It is well connected by regular bus services. 	

3. Property Type



4. Property Use ABANDONED / IN USE : Abandoned Present Memorial 2 Memorial Past • 5. Age (Source) 17th Century A.D. PERIOD : YEARS : Precise date of Construction 2 Completion : Subsequent changes : **Destruction / Demolition** : 6. Ownership / Level of Protection SINGLE /MULTIPLE : **Public** : Archaeological Survey of : India / State Archaeology Department / Any Other (Please specify) Private 2 Any other (Please specify) : Name 2 Address 2 Phone ÷ 7. Association WITH EVENTS In History Memorial : In Rituals 2 In Building Construction : Any other (specify) : WITH PERSONS Patron 2 **Architect / Engineer** 2 Any other (specify) : 8. Statement of Significance Architectural Domical superstructure Archaeological Historical

Religious

Any other (specify)

SECTION II: DESCRIPTION

9.	Physical Description and De	cor	ative Features
•	Context Urban / Rural Setting Surroundings		 * Drawings (Attach extra sheet if necessary) Rural Settings Stand in Isolation
			Integral part of a Landscape / Street / Complex
•	Quantification Area Dimension (L x B x H)	:	(m / om / foot / in ch)
	Number of Blocks Number of Storys	:	(m / cm/ feet / inch) 01 01
•	Spatial Organization Orientation Plan Allocation of Spaces	:	The Chhatri is oriented East-West and faces the East
•	CHITECTURAL STYLE Ornamentation Exteriors Interiors Movable Collections by Other (specify)	:	Canopied chhatri.

10. Construction Technology

Structural System		Indo-Persian
Building Techniques	:	Arcuate system
Material of Construction	:	Stone and plaster

11. Condition Assessment

In General Good / Fair Good

Sign of Deterioration Serious Deterioration Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Blackening of surface, Algae formation

12. Threats to the Property

Natural Negligence Vandalism Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS